



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

| | |
|------------------|--|
| Involving | TPVD (SKS1919M) |
| Date of Loss | 24 June 2020 |
| Time of Loss | 18.40 |
| Loss Description | SJE8298K (INSD) C/W SKS1919M (TP / AXA SOM02PVP) |
| Comment | |

Workshop Details

| | |
|---------------------------|-----------------------------------|
| Total Rebate Amount | 63119 |
| Nett Loss Amount | -\$63,119.00 |
| Assigned Workshop | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Days of work completion * | 20 |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

| | | | |
|-----------------------|----------------------|---------------------|-----------------------------------|
| Vehicle Registration# | SKS1919M | Purchase Date | <div>dd/mm/yyyy</div> <div></div> |
| Registration State | <div>SINGAPORE</div> | Registration Date * | <div>30/03/2015</div> <div></div> |
| Mileage | <div></div> | Age of Vehicle | 5 |

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|--------------------|--------------------|-------------------------------------|
| Manufacturing Year | | <div>2014</div> |
| Make | TPVD | <div>AUDI</div> |
| Model | | <div>S3 SEDAN 2.0 TFSI QU (I-</div> |
| Type | | <div></div> <div>▾</div> |

Driver Details

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|---------------|-------------------------|-----------------------------------|
| Driver Name | JEREMY TAN CHANG HUI | <div></div> |
| Date of Birth | | <div>dd/mm/yyyy</div> <div></div> |
| Age | 0 | |

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|-----------------|--------------------|------------------------|
| Type of Paint | | |
| Chassis No | | WAUZZZ8V4F1089573 |
| Engine No | | CJX045329 |
| Engine Capacity | | 1984 |
| Sum Insured | | 0 |
| Market Value | | 0 |

| Occupation CATEGORY | Unknown FNOL INFORMATION | INFORMATION |
|-------------------------|--------------------------|-------------|
| Education Qualification | Other | |
| Driving Experience | 0 | |
| Driver License # | | |
| License Type | | |
| License Issue Date | | dd/mm/yyyy |
| License Expiration Date | | dd/mm/yyyy |
| Address | TBC, Singapore | |
| Address type | Personal Correspondence | |

Gender
CATEGORY

Unknown
FNOL INFORMATION

▼

INFORMATION

Marital status

Unknown

▼

Identification #

TBC



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

01/12/2020



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40R18

Rear Tyre Size

225/40R18

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

| | | | |
|-------------|---------------------------------|-------------|----------------------------------|
| Depr./Bttr% | <input type="text"/> | Salvage% | <input type="text"/> |
| Discount% | <input type="text" value="10"/> | Settlement% | <input type="text" value="100"/> |

Paint Labour/Material Ratio

| | | | |
|--------------------|---------------------------------|----------------------|---------------------------------|
| Paint Labour Ratio | <input type="text" value="20"/> | Paint Material Ratio | <input type="text" value="80"/> |
|--------------------|---------------------------------|----------------------|---------------------------------|

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

























Add





























Approve





























Deny















Submit All

| | EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMARKS |
|--------------------------|------|-------|-----------|----------|---------------------------------|-----------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|----------------|---------|
| <input type="checkbox"/> | | 0 | 1 | | FRONT BUMPER | Replaced | 0 | 1473.6 | No | | 10 | | | 1326.24 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | FRONT BUMPER REINFORCEMENT | Replaced | 0 | 613 | No | | 10 | | | 551.7 | Reviewing | |
| <input type="checkbox"/> | | 0 | 2 | | FRONT BUMPER SIDE RETAINER | Replaced | 0 | 35 | No | | 10 | | | 63 | Reviewing | |
| <input type="checkbox"/> | | 0 | 10 | | FRONT BUMPER CLIP | Replaced | 0 | 5 | No | | 10 | | | 45 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | LH HUD XENON HEADLAMP ASSY | Replaced | 0 | 1210 | No | | 10 | | | 1089 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | LH HEADLAMP SPRAY JET | Replaced | 0 | 270 | No | | 10 | | | 243 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | LH HID HEADLAMP SPRAY JET COVER | Replaced | 0 | 70 | No | | 10 | | | 63 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | RH HID XENON HEADLAMP ASSY | Replaced | 0 | 1210 | No | | 10 | | | 1089 | Reviewing | |
| <input type="checkbox"/> | | 0 | 1 | | SET FRONT GRILLE C/LOGO | Replaced | 0 | 900 | No | | 10 | | | 810 | Reviewing | |

| | EDIT | SR NO | QUANTITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISCOUNT% | SALVAGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMARKS |
|--------------------------|---|-------|----------|----------|------------------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|-----------|----------|------------------|-----------------|----------------|---|
| <input type="checkbox"/> |  | 0 | 8 | | SET FRONT GRILLE CLIP | Replaced | 0 | 5 | No | | 10 | | | 36 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | FRONT NUMBER PLATE HOLDER | Replaced | 0 | 86 | No | | 10 | | | 77.4 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH FRONT FENDER | Replaced | 0 | 641.2 | No | | 10 | | | 577.08 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH FRONT FENDER SPLASH SHIELD | Replaced | 0 | 225 | No | | 10 | | | 202.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 8 | | LH FRONT FENDER SPLASH SHIELD CLIP | Replaced | 0 | 5 | No | | 10 | | | 36 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH FRONT SHOCK ABSORBER | Replaced | 0 | 1438 | No | | 10 | | | 1294.2 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT SHOCK ABSORBER | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH FRONT SUSPENSION LOWER ARM | Replaced | 0 | 239 | No | | 10 | | | 215.1 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT SUSPENSION LOWER ARM | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH FRONT DRIVER SHAFT | Replaced | 0 | 1752 | No | | 10 | | | 1576.8 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT DRIVER SHAFT | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 2 | | LH / RH FRONT STEERING KNUCKLE | Replaced | 0 | 625 | No | | 10 | | | 1125 | Reviewing |  |

| | EDIT | SR NO | QUANTITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISCOUNT% | SALVAGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | RE |
|--------------------------|---|-------|----------|----------|--|-------------|-----------------------|-----------------------|---------------------|--------------|-----------|----------|------------------|-----------------|----------------|---|
| <input type="checkbox"/> |  | 0 | 2 | | LH / RH FRONT WHEEL BEARING C/W HUB ASSY | Replaced | 0 | 469.25 | No | | 10 | | | 844.65 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH STABILISER BAR LINK | Replaced | 0 | 151 | No | | 10 | | | 135.9 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH STABILISER BAR LINK | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH STEERING TIE ROD | Replaced | 0 | 135 | No | | 10 | | | 121.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH STEERING TIE ROD END | Replaced | 0 | 112 | No | | 10 | | | 100.8 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | LH SUSPENSION BALL JOINT | Replaced | 0 | 105 | No | | 10 | | | 94.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH SUSPENSION BALL JOINT | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | FRONT STABILIZER BAR | Replaced | 0 | 385 | No | | 10 | | | 346.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | STEERING RACK & PINION ASSY | Replaced | 0 | 4225 | No | | 10 | | | 3802.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | FRONT SUSPENSION CROSS MEMBER | Replaced | 0 | 1505 | No | | 10 | | | 1354.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | ENGINE FRONT SPLASH COVER | Replaced | 0 | 128 | No | | 10 | | | 115.2 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | ENGINE SIDE SPLASH COVER LH | Replaced | 0 | 95 | No | | 10 | | | 85.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | SET HORN | Replaced | 0 | 155 | No | | 10 | | | 139.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT FENDER | Replaced | 0 | 641.2 | No | | 10 | | | 577.08 | Reviewing |  |

| | EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REN |
|--------------------------|---|----------|--------------|----------|--|-------------|--------------------------|--------------------------|------------------------|-----------------|---------------|--------------|---------------------|--------------------|-------------------|---|
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT FENDER SPLASH SHIELD | Replaced | 0 | 225 | No | | 10 | | | 202.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 8 | | RH FRONT FENDER SPLASH SHIELD CLIP | Replaced | 0 | 5 | No | | 10 | | | 36 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT DOOR | Repair | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | RH FRONT DOOR OUTER HANDLE | Replaced | 0 | 135 | No | | 10 | | | 121.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR WHEEL BEARING C/W HUB ASSY | Replaced | 0 | 529.6 | No | | 10 | | | 476.64 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR SHOCK ABSORBER RH | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR TRAILING ARM RH | Serviceable | 0 | 0 | No | | 10 | | | 0 | Deny |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR WHEEL CARRIER RH | Replaced | 0 | 1020 | No | | 10 | | | 918 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR DOOR RH | Replaced | 0 | 2520 | No | | 10 | | | 2268 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR RH DOOR OUTER HANDLE | Replaced | 0 | 128 | No | | 10 | | | 115.2 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR BUMPER | Replaced | 0 | 1250 | No | | 10 | | | 1125 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR BUMPER SIDE BRACKET RH | Replaced | 0 | 96 | No | | 10 | | | 86.4 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 10 | | REAR BUMPER CLIP | Replaced | 0 | 5 | No | | 10 | | | 45 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | TAILLAMP ASSY RH | Replaced | 0 | 580 | No | | 10 | | | 522 | Reviewing |  |

| | EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | RE |
|--------------------------|---|-------|-----------|----------|-----------------------------------|-----------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|----------------|---|
| <input type="checkbox"/> |  | 0 | 1 | | REAR FENDER RH | Replaced | 0 | 1688 | No | | 10 | | | 1519.2 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR RH FENDER SPLASH SHIELD | Replaced | 0 | 155 | No | | 10 | | | 139.5 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 10 | | REAR RH FENDER SPLASH SHIELD CLIP | Replaced | 0 | 5 | No | | 10 | | | 45 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | SET REAR WINDSCREEN C/W MOULDING | Replaced | 0 | 942 | No | | 10 | | | 847.8 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | FRONT SPORT RIM LH | Replaced | 0 | 1350 | No | | 10 | | | 1215 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | FRONT SPORT RIM RH | Replaced | 0 | 1350 | No | | 10 | | | 1215 | Reviewing |  |
| <input type="checkbox"/> |  | 0 | 1 | | REAR SPORT RIM RH | Replaced | 0 | 1350 | No | | 10 | | | 1215 | Reviewing |  |







Labour













Add

Approve

Deny

Submit All

| | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | RE |
|--------------------------|---|-------|-------------------------|---|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|---|
| <input type="checkbox"/> |  | 0 | | TO CHECK WIRING | 0 | 60 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | | TO APPLY ANTI-RUST UNDERCOAT | 0 | 100 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | | TO ALIGN HEADLAMPS AND FOCUS HEADLAMP BEAMS TO LTA SPECIFICATIONS | 0 | 60 | 0 | 0 | Reviewing | |  |

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | REN |
|--------------------------|---|----------------------------|--|---------------------------|---------------------------|--------------------------|--------------------------|--------------------|---------|---|
| <input type="checkbox"/> |  | 0 | TO REMOVE, RENEW AND INSTALL STEERING RACK & PINION ASSY AND TO ALIGN STEERING GEOMETRY AND CENTRELISE STEERING WHEEL. TO HOOK UP ECU TO DIAGNOSTIC SCANNER, PROGRAMME AND SET STEERING ANGLE POSITION | 0 | 450 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | TO REMOVE AND REPLACE FRONT LH / RH SUSPENSION PARTS, SUSPENSION CROSS MEMBER, ETC | 0 | 500 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | TO CONDUCT COMPUTERISED 4- WHEEL ALIGNMENT TO RESET WHEEL ALIGNMENT | 0 | 90 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | TO REMOVE AND REFIT REAR PASSENGER, REAR FENDER INNER TRIM COVER AND FITTINGS, AFFECTED UPHOLSTERY AND CARPET, ETC TO FACILITATE THE NECESSARY REPAIRS | 0 | 250 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE NECESSARY REPAIRS | 0 | 120 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS | 0 | 2375 | 0 | 0 | Reviewing | |  |

| EDIT | | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | REMARKS |
|--------------------------|---|----------|----------------------------|--|---------------------------|---------------------------|--------------------------|--------------------------|--------------------|---------|---|
| <input type="checkbox"/> |  | 0 | | SPRAY PAINTING CHARGES TO PAINT THE REAR BUMPER, REAR RH FENDER, REAR RH DOOR, FRONT RH DOOR, RH WING MIRROR, RH FRONT FENDER, FRONT BUMPER, LH FRONT FENDER, LH WINDSCREEN PILLAR AND NECESSARY AREAS | 0 | 2250 | 0 | 0 | Reviewing | |  |
| <input type="checkbox"/> |  | 0 | | TOWING AND RECOVER SERVICES (KING DOLLY) | 0 | 150 | 0 | 0 | Reviewing | |  |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

















Add









Approve

Deny

Submit All

| | EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|--------------------------|------|-------|------------------------------------|-----------|------------------|-----------------|----------|--------|
| <input type="checkbox"/> | | 0 | DAYS OF REPAIR : 22 DAYS | Reviewing | | 0 | | |
| <input type="checkbox"/> | | 0 | CARBON FRIBRE FRONT BONNET | Reviewing | | 1280 | REPLACED | |
| <input type="checkbox"/> | | 0 | CARBON FIBRE FRONT BUMPER LIP | Reviewing | | 580 | REPLACED | |
| <input type="checkbox"/> | | 0 | CARBON FIBRE FRONT BUMPER DIFFUSER | Reviewing | | 380 | REPLACED | |

| <input type="checkbox"/> |  | SR No | CABIN FIBRE SIDE SKIRT | ACTION Reviewing | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT REPLACED |  OVE |
|--------------------------|---|----------|---|---------------------|---------------------|--------------------|---|---|
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| <input type="checkbox"/> |  | 0 | CARBON FIBRE AIR FILTER HOUSING COVER | Deny | | 0 | NOT NECESSARY |  |
| <input type="checkbox"/> |  | 0 | LH FOG LAMP ASSY | Reviewing | | 250 | REPLACED |  |
| <input type="checkbox"/> |  | 0 | LH FOG LAMP GARNISH | Reviewing | | 125 | REPLACED |  |
| <input type="checkbox"/> |  | 0 | RH FOG LAMP ASSY | Deny | | 0 | NOT NECESSARY |  |
| <input type="checkbox"/> |  | 0 | RH FOG LAMP GARNISH | Deny | | 0 | NOT NECESSARY |  |
| <input type="checkbox"/> |  | 0 | FOG LAMP BULB SOCKET (2 PCS) | Reviewing | | 35 | O/S NOT NECESSARY / N/S REPLACED |  |
| <input type="checkbox"/> |  | 0 | TURBO INTERCOOLER | Reviewing | | 1300 | REPLACED |  |

| | EDIT | SR NO | NAME TURBO | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|--------------------------|---|----------|--|-----------|---------------------|--------------------|----------|---|
| <input type="checkbox"/> |  | 0 | INTERCOOLER GRILLE | Reviewing | | 95 | REPLACED |  |
| | | | | | | | | |
| <input type="checkbox"/> |  | 0 | TURBO INTERCOOLER BRACKET | Reviewing | | 155 | REPLACED |  |
| | | | | | | | | |
| <input type="checkbox"/> |  | 0 | TURBO INTERCOOLER TRIPLE HOSE CONNECTOR | Reviewing | | 85 | REPLACED |  |
| | | | | | | | | |
| <input type="checkbox"/> |  | 0 | REAR TYRE RH | Reviewing | | 350 | REPLACED |  |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$41,890.89

| CATEGORY | ESTIMATE | ADJUSTED |
|---------------|----------|-------------|
| Spare Parts | \$0.00 | \$30,250.89 |
| Labour | \$0.00 | \$6,405.00 |
| Miscellaneous | \$0.00 | \$5,235.00 |

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|--------------------------|-------|------|----------------|------------------|-----------------|---------|--------|
| <input type="checkbox"/> | | 0 | FINAL LUMP SUM | Reviewing | 33500 | | |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$33,500.00

| CATEGORY | ESTIMATE | ADJUSTED |
|---------------|----------|-------------|
| Miscellaneous | \$0.00 | \$33,500.00 |

Submit for Review