

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012790/KRA3Q2

**Date:** 23/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700031881

**Claimant**  
**Vehicle No :** SKV3655U **Insured Vehicle No :** SJU7862D

Date of Loss: 18/11/2020 Nature of Claim: TP Claim No: 8303064081SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKV3655U</b>	Engine No:	1ZRX522980
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104536327
Reg. Date:	15/09/2015 (Man. Year: 2015)	Odometer:	88332 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,645.05	9,232.85	9,412.20	50.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	1,890.00	2,530.00	57.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,065.05</b>	<b>11,122.85</b>	<b>11,942.20</b>	<b>51.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>23,065.05</b>	<b>8,900.00</b>	<b>14,165.05</b>	<b>61.41</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>9,267.45</b>		

### INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 20/11/2020 Inspected At:

Caris Autoworks Pte Ltd (HQ)  
#05-03 160SIN MING DRIVE  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER (FRONT)	Bent / Cracked	458.10 F	*458.10 FL
2	1		*BUMPER REINFORCEMENT (FRONT)	Bent	379.20 F	*379.20 FL
3	1		*BUMPER ENERGY (FRONT)	Cracked	85.20 F	*85.20 FL
4	1		*BUMPER FOG LAMP (FRONT LEFT)	Serviceable	248.20 F	*- FL
5	1		*BUMPER FOG LAMP COVER (FRONT LEFT)	Serviceable	102.20 F	*- FL
6	1		*GRILLE (FRONT)	Cracked	559.60 F	*399.10 FL
7	2		*BUMPER SIDE SUPPORT (FRONT)	Serviceable	151.80 F	*- FL
8	1		*BONNET (FRONT)	Buckled	1,028.10 F	*1,028.10 FL
9	2		*MANGUARD (FRONT)	Repair	1,474.20 F	*- FL
10	1		*BUMPER RETAINER (FRONT LEFT)	Distorted	45.90 F	*45.90 FL
11	2		*BONNET HINGE (FRONT)	Bent	59.50 F	*59.50 FL
12	1		*BONNET LOCK (FRONT)	Distorted	128.90 F	*128.90 FL
13	1		*FENDER (FRONT LEFT)	Serviceable	168.90 F	*- FL
14	2		*HEADLAMP(FRONT)	O/S Mtg Cracked / N/S Cracked	5,629.00 F	*5,136.20 FL
15	1		*RADIATOR	Punctured	1,764.00 F	*1,510.50 FL
16	1		*RADIATOR FAN MOTOR	Jammed / Cracked	421.50 F	*421.50 FL
17	1		*AIR CON CONDENSER	Punctured	1,404.39 F	*1,289.24 FL
18	1		*ENGINE MOUNTING (FRONT LEFT)	Serviceable	200.70 F	*- FL
19	1		*ENGINE MOUNTING (FRONT)	Distorted	188.86 F	*188.86 FL
20	1		*LOWER ARM (FRONT LEFT)	Serviceable	251.40 F	*- FL
21	1		*WHEEL BEARING (FRONT LEFT)	Not Necessary	119.00 F	*- FL
22	1		*WHEEL KNUCKLE (FRONT LEFT)	Serviceable	441.70 F	*- FL
23	1		*S/ABSORBER (FRONT LEFT)	Serviceable	356.90 F	*- FL
24	1		*S/ABSORBER MOUNTING (FRONT LEFT)	Serviceable	169.80 F	*- FL
25	1		*RIM (FRONT LEFT)	Serviceable	1,644.50 F	*- FL
26	1		*BODY CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*SUPPORT PANEL ASSY	Bent	977.60 F	*977.60 FL
28	1		*AIR FILTER HOUSING	Cracked	135.90 F	*135.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 18,645.05 12,293.80**  
**- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 3,060.95**

**Total Parts (\$\$) 18,645.05 9,232.85**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL KNOCKING	New	1,800.00	700.00
2	SPRAY PAINTING	New	1,500.00	1,000.00
3	WHEEL ALIGNMENT (COMPUTRISED)	New	120.00	0.00
4	WIRE CHECKING & DIAGNOSTIC	New	150.00	20.00
5	TOWING	New	100.00	50.00
6	LABOUR FOR REPLACING RADIATOR & OTHER PARTS	New	650.00	50.00
7	AIR CON GAS TOP UP	New	50.00	50.00
8	RADIATOR COOLANT	New	50.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>4,420.00</b>	<b>1,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >