

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012796/ERA3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100261192
Claimant Vehicle No :	SHA7049P	Insured Vehicle No :	GW8512H
Date of Loss:	19/11/2020	Nature of Claim:	TP
		Claim No:	4609608290SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7049P		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDGU668500
Reg. Date:	14/05/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMFU069055
Colour:	Blue	Odometer:	886207 km
Engine Capacity:	1680 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,902.44	2,902.44	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,020.00	280.00	21.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,202.44	3,922.44	280.00	6.66
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	4,202.44	3,150.00	1,052.44	25.04
+ GST 7.00/7.00% (S\$)	294.17	220.50	73.67	25.04
Nett Amount (S\$)	4,496.61	3,370.50	1,126.11	25.04
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$110.67/day) (S\$)		276.68		
(S\$)		3,747.18		
Liable Amount (50.00%) (S\$)		1,873.59		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,875.59		
Global Sum Settlement (S\$)		1,850.00		

INSPECTION

Date of Assignment:	20/11/2020	
Date Inspected:	20/11/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY -HEAD RH	Broken	1,388.00 FL	*1,388.00 FL
2	1		*BRACKET -FR BUMPER S	Broken	24.60 FL	*24.60 FL
3	10		*HYUNDAI BUMPER COVER CLIP	Necessary	20.00 FL	*20.00 FL
4	1		*PANEL -FENDER RH	Dented	663.00 FL	*663.00 FL
5	1		*CAP ASSY -WHEEL HUB	Cut	217.20 FL	*217.20 FL
6	1		*COVER -FR BUMPER	Broken	1,052.20 FS	*1,052.20 FS
					Sub Total (\$\$)	3,365.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	462.56
					Total Parts (\$\$)	2,902.44

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	560.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
5	RENEW ADVERTISEMENT STICKER -FENDER	New	100.00	0.00
Gross Labour Cost (\$)			1,300.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >