

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012797/QQF3E2

Date: 15/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00109022001

Claimant Vehicle
No : GBJ2976U

Insured Vehicle
No : SGQ9116T

Date of Loss: 19/11/2020

Nature of Claim: TP

Claim
No: SNM20D204476/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ2976U

Make & Model: KIA K2500 6M/T, 2.5 D (M)

Reg. Date: 11/03/2019 (Man. Year: 2019)

Colour: White

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: D4CBK734427

Chassis No: KNCSJX76LK7340960

Odometer: 53391 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Front Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Tyre Size: 195 R15C

Rear Left Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,930.53	3,959.23	6,971.30	63.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,650.00	2,650.00	61.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,230.53	5,609.23	9,621.30	63.17
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	15,230.53	4,500.00	10,730.53	70.45
+ GST 7.00/7.00% (\$\$)	1,066.14	315.00	751.14	70.45
Nett Amount (\$\$)	16,296.67	4,815.00	11,481.67	70.45

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 20/11/2020 Inspected At:

Estimated Period of Repair: 5.0 days

60 Jalan Lam Huat, Carros Centre #05-21
Repairer : My Car Consultant (HQ)

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Dec 2020)	
Parts:	N/A	KIA K2500 6M/T 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2976U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,798.00 FL	*1,525.00 FL
2	2		*TAILGATE SAFETY LOCK	Serviceable	428.00 FL	*- FL
3	1		*TAILGATE LOWER END PANEL	Serviceable	812.00 FL	*- FL
4	3		*TAILGATE HINGES	Serviceable	195.00 FL	*- FL
5	1		*TAILGATE KIA MOTOR STICKER	Necessary	240.70 FL	*240.70 FL
6	2		*TAILLAMP BRACKET	Bent	582.00 FL	*356.00 FL
7	2		*TAILLAMP	Cracked	824.00 FL	*450.00 FL
8	1		*REAR CROSSMEMBER	Serviceable	1,125.00 FL	*- FL
9	1		*REAR EXHAUST PIPE	Serviceable	712.00 FL	*- FL
10	1		*REAR SPARE TYRE BRACKET	Serviceable	312.00 FL	*- FL
11	1		*REAR NUMBER PLATE LAMP	Crumpled	124.00 FL	*124.00 FL
12	1		*REVERSE BUZZER	Shorted	159.00 FL	*159.00 FL
13	1		*REAR NUMBER PLATE	Crumpled	50.00 FS	*50.00 FS
14	1		*REVERSE SENSOR WITH HOLDER	Shorted	300.00 FS	*200.00 FS
15	1		*TAILGATE ALUMINIUM PLATE	Serviceable	800.00 FS	*- FS
16	1		*REAR FLOOR PANEL ALUMINIUM PLATE	Dented	1,200.00 FS	*200.00 FS
17	1		*TAILGATE STICKER 70KM	Necessary	50.00 FS	*20.00 FS
18	1		*TAILGATE STICKER 13PAX	Necessary	50.00 FS	*20.00 FS
19	1		*REAR LOWER SAFETY BAR	Bent	1,500.00 FS	*900.00 FS
20	2		*REAR LOWER SAFETY BAR BRACKET	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,661.70	4,244.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	731.17	285.47
Total Parts (\$\$)	10,930.53	3,959.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
3	REMOVE AND REFIX TAILGATE ALUMINIUM PLATE	New	300.00	100.00
4	REMOVE AND REFIX TAILGATE MECHANISM	New	150.00	30.00
5	TO WELD SAFETY BAR	New	200.00	100.00
6	TO RESPRAY UNDERCOATING	New	100.00	30.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	600.00
9	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	700.00
Gross Labour Cost (\$\$)			4,300.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >