Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012798/AGCD3Q2

Date: 02/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001401706

Claimant

SBR883A Insured Vehicle No: SBW8893S

Vehicle No: SBR883A Insured Vehicle No: SBW88935

Date of Loss: 19/11/2020 Nature of Claim: TP Claim No: 249988

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBR883A

Make & Model: NISSAN SUNNY, 1.6 EX (M) Engine No: QG16420176

Reg. Date: 11/01/2007 (Man. Year: 2007) Chassis No: JN1CFAN16Z0106037

Colour: Red Odometer: 182733 km

Engine Capacity: 1597 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,764.48	3,106.17	3,658.31	54.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,270.00	1,140.00	33.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,174.48	5,376.17	4,798.31	47.16
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	10,174.48	4,300.00	5,874.48	57.74
+ GST 7.00/7.00% (S\$)	712.21	301.00	411.21	57.74
Nett Amount (S\$)	10,886.69	4,601.00	6,285.69	57.74

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 20/11/2020 Inspected At: J-mart Motor Pte Ltd (HQ)

Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2021)

Parts: 143 NISSAN SUNNY 1.6 EX (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBR883A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

Amount

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qty Part No. Particulars

140.	Qty	i ditito.	r ai ticulai 5	Condition	ixepairer 5	Aillouilt
1	1		*BOOTLID	Buckled	774.00 FN	*655.00 FN
2	1		*SUNNY EMBLEM	Necessary	89.00 FN	*55.00 FN
3	1		*NISSAN EMBLEM	Necessary	50.70 FN	*50.70 FN
4	1		*EX SALOON EMBLEM	Necessary	89.00 FN	*53.00 FN
5	1		*CTVC EMBLEM	Necessary	89.00 FN	*45.00 FN
6	1		*E-THROTTE EMBLEM	Necessary	89.00 FN	*48.00 FN
7	1		*BOOTLID LOCK	Damaged	127.00 FN	*88.50 FN
8	1		*BOOTLID W/STRIP	Cut	97.40 FN	*97.40 FN
9	1		*BOOTLID TOP CHROME	Not Necessary	369.10 FN	*- FN
10	1		*BOOTLID LOWER CHROME	Cut	229.80 FN	*173.80 FN
11	2		*TAILLAMP	Cut	920.54 FN	*566.40 FN
12	1		*REAR BUMPER	Distorted	552.50 FN	*452.50 FN
13	1		*REAR BUMPER RETAINERS (4 Pcs)	Damaged (2 Pcs only)	146.40 FN	*70.00 FN
14	1		*REAR BUMPER CHROME	Deformed	175.20 FN	*175.20 FN
15	1		*REAR BUMPER BRACKET	O/s Dented	190.40 FN	*95.20 FN
16	1		*REAR BUMPER SPONGE	Cracked	139.00 FN	*139.00 FN
17	1		*END PANEL	Dented	634.40 FN	*398.20 FN
18	1		*END PANEL INNER GARNISH	Deformed	144.10 FN	*85.00 FN
19	2		*REAR FENDER INNER TRIM RH/LH	Not Necessary	446.60 FN	*- FN
20	1		*SPARE TYRE CARDBOARD	Torn	497.50 FN	*203.40 FN
21	1		*SPARE TYRE PANEL	Repair	757.00 FN	*- FN
22	1		*EXHAUST PIPE	Repair	864.00 FN	*- FN
23	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
F=Fra	anchise	part. S=Spcl	Nett. N=NettItemDisc.	e		
				Sub Total (S\$)	7,511.64	3,451.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)					747.16	345.13

Report was unsubmitted during this print-out.

Total Parts (S\$)

6,764.48

3,106.17

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,500.00	1,000.00
2	SPRAY PAINTING	New	1,600.00	1,000.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	80.00
5	UPHOLSTERY	New	120.00	80.00
6	REMOVE & REFIT EXHAUST PIPE	New	80.00	80.00
		Gross Labour Cost (S\$)	3,410.00	2,270.00
	Report w	as unsubmitted during this print-out.		

< END OF ESTIMATES >