



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 2596R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRUMPLED	898.00	898.00
1	FRONT BUMPER REINFORCEMENT	BENT	398.00	398.00
2	FRONT BUMPER SIDE RETAINER @\$21.00	BROKEN	42.00	42.00
1	FRONT BUMPER SIDE GRILLE LH	SERVICEABLE	112.00	-
1	FRONT BUMPER LOWER COVER	SERVICEABLE	312.00	-
1	FRONT BUMPER LOWER GRILLE	CRUMPLED	289.00	220.00
1	FRONT GRILLE	CUT	498.00	380.00
1	FRONT GRILLE BASE	SERVICEABLE	512.20	-
1	FRONT GRILLE CHROME MOULDING	CRUMPLED	422.60	380.00
1	FRONT GRILLE LOGO	NECESSARY	76.20	76.20
1	HEADLAMP LH	CRUMPLED	1,598.30	1,230.00
1	HEADLAMP LOWER BRACKET LH	CRUMPLED	91.60	91.60
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	598.00	-
1	FRONT FENDER INNER SHIELD LH	CRUMPLED	145.00	145.00
1	FRONT FENDER EMBLEM 'HYBRID' LH	SERVICEABLE	89.00	-
1	FRONT SUPPORT PANEL	SERVICEABLE	749.20	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	214.00	-
	LESS 20% DISCOUNT		-1,409.02	-772.16
			5,636.08	3,088.64
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT FENDER SEALANT RH (SN)	SERVICEABLE	80.00	-
1	FRONT FENDER QUATER GLASS SEALANT RH (SN)	SERVICEABLE	80.00	-
			210.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	TO RESPRAY UNDERCOATING.		150.00	30.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	300.00

Report Ref No. CS/AGI20012799/Qqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		800.00	400.00
			2,030.00	790.00
GRAND TOTAL			7,876.08	3,908.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/AGI20012799/Qqf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.