

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 133007136R GS1 Reg. No. 13-3007136-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI20012799/Qqf3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	11/01/2021	
			C	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMF 1936H	Veh. Inspected		SMQ 2596R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008022/LA	Excess (\$)		0.00	
	Assign From	STANLEY LAI	Assign Date		20/11/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE HYBRID	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GP72006785	Colour		RED	
	Odometer	75462 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	FIRENZA		6 mm	
	L/H Front Tyre	185/60 R15	FIRENZA		6 mm	
	R/H Rear Tyre	185/60 R15	FIRENZA		6 mm	
	L/H Rear Tyre	185/60 R15	FIRENZA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	17/11/2020	Inspection Date		20/11/2020	
	Survey held at 60 JALAN LAM HUAT, CARROS CENTRE #05-21 S(737869)					
	Repairer	MY CAR CONSULTANT PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days