Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20012800/R1PS3Q2

Date: 10/02/2021

Odometer:

REFERENCE

India International Insurance Handling Insurer:

Pte Ltd

Policy No: D19MPC0000362 01

Claimant Vehicle No:

SMV7676J

Insured Vehicle No:

SMF9623H

Date of Loss: 19/11/2020 Nature of Claim: TP Claim No:

2363 km

MPC2020D0002429

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV7676J**

Make & Model: BMW 320I, 2.0 SEDAN LED NAV (A) Engine No: F0083639B48B20A Reg. Date: 20/10/2020 (Man. Year: 2020) Chassis No: WBA5F32080FJ64240

Colour: Blue

Engine Capacity: 1998 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,256.60	1,883.00	373.60	16.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,923.60	3,967.00	956.60	19.43
+ GST 7.00/7.00% (S\$)	344.65	277.69	66.96	19.43
Nett Amount (S\$)	5,268.25	4,244.69	1,023.56	19.43

+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$) 385.20 + Doc/Search Fee (S\$) 2.00

> **Nett Liability (S\$)** 4,631.89

INSPECTION

Date of Assignment: 01/12/2020

Date Inspected: 01/12/2020 Inspected At: Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)		
Parts:	143	BMW 320I 2.0 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SMV7676J)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*TAILPIPE TRIM CHROME D=90MM	Serviceable	124.00 FS	*- FS
3	1		*REAR BUMPER CARRIER	Bent	479.65 FS	*479.65 FS
4	1		*ADAPTER	Cracked	48.40 FS	*48.40 FS
5	1		*REAR BUMPER LH SIDE GUIDE	Serviceable	58.25 FS	*- FS
6	1		*REAR BUMPER LH TRIM PANEL REAR TOP	Serviceable	95.35 FS	*- FS
7	1		*REAR BUMPER LH BOTTOM TRIM PANEL (L)	Serviceable	96.00 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (BASIS PDC)	Deformed	1,274.95 FS	*1,274.95 FS
F=Fra	nchise	part. S=Spcl	Nett.			
				Total Parts (S\$)	2,256.60	1,883.00
				,		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	TO PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING RECONNECT TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labour	r Cost (S\$)	2,667.00	2,084.00
Γ	Report was unsubmitted durin	a this print-out.		1

< END OF ESTIMATES >