

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI20012805/R1QF3Q2**Date:** 05/02/2021**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant****Vehicle No :** SMJ2674K**Insured Vehicle No :** YQ383J

Date of Loss: 18/11/2020

Nature of Claim:

TP

Claim No: CDMCG20001703

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMJ2674K**

Make &amp; Model: BMW X2, 1.5 SDRIVE18I (A)

Engine No: 35845388B38A15A

Reg. Date: 27/02/2019 (Man. Year: 2018)

Chassis No: WBAYH12030EM91825

Colour: White

Odometer: 30024 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R19

Rear Tyre Size:

225/45 R19

Front Left Side: Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side:

Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,234.15	4,737.75	496.40	9.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,660.00	9,397.00	2,263.00	19.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,894.15</b>	<b>14,134.75</b>	<b>2,759.40</b>	<b>16.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,182.59</b>	<b>989.43</b>	<b>193.16</b>	<b>16.33</b>
<b>Nett Amount (S\$)</b>	<b>18,076.74</b>	<b>15,124.18</b>	<b>2,952.56</b>	<b>16.33</b>

**INSPECTION**

Date of Assignment: 20/11/2020

Date Inspected: 07/12/2020 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2021)
<b>Parts:</b>	M1-SUV	BMW X2 1.5 SDRIVE18I (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ2674K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL TRIM	Scratched	403.75 FS	*403.75 FS
2	2		*WASHER GASKET	Serviceable	22.40 FS	*- FS
3	1		*REAR BUMPER LH SIDE INNER GUIDE	Cracked	61.35 FS	*61.35 FS
4	1		*REAR BUMPER CARRIER	Bent	511.10 FS	*511.10 FS
5	1		*REAR BUMPER LH SIDE GUIDE (M)	Cracked	73.60 FS	*73.60 FS
6	1		*MOUNTING SMART OPENER (M)	Serviceable	45.55 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (M PDC/ICA)	Deformed	1,185.70 FS	*1,185.70 FS
8	1		*REAR BUMPER TRIM PANEL BOTTOM PAINT	Scratched	514.10 FS	*514.10 FS
9	1		*TRIM TAILGATE BOTTOM PRIMED	Deformed	474.80 FS	*474.80 FS
10	1		*LETTERING X2	Not Necessary	64.45 FS	*- FS
11	1		*LETTERING S DRIVE 18I	Not Necessary	96.65 FS	*- FS
12	1		*TRUNK LID SEALING	Serviceable	170.20 FS	*- FS
13	1		*REAR LH LIGHT IN THE SIDE PANEL	Cracked	471.55 FS	*471.55 FS
14	1		*REAR LH LIGHT IN TRUNK LID	Cracked	330.10 FS	*330.10 FS
15	1		*LH TAIL LIGHT FINISHER	Serviceable	62.55 FS	*- FS
16	1		*BLIND RIVET AVIBVLB (25 Pcs)	Necessary	16.50 FS	*16.50 FS
17	6		*SCREW (SF PLUS M5X15)	Not Necessary	3.30 FS	*- FS
18	1		*(S/L) CLEANER R2 500ML	Not Necessary	14.80 FS	*- FS
19	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	331.80 FS	*331.80 FS
20	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
21	1		*PUNCH RIVET N4 (50 Pcs)	Necessary	27.50 FS	*11.00 FS
22	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
23	20		*EXPANDING RIVET BLACK	Necessary	28.00 FS	*28.00 FS
24	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	114.45 FS	*114.45 FS
25	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **5,234.15**      **4,737.75**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE REAR BUMPER,BOOT LID,TAIL PANEL AND ATTACHMENTS	New	6,800.00	5,100.00
2	TO PAINTING REAR BUMPER,TAILGATE,TAIL PANEL AND TRUNK FLOOR	New	3,350.00	3,015.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	230.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
<b>Gross Labour Cost (\$)</b>			<b>11,660.00</b>	<b>9,397.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >