11/1/21, 10:52 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20012810/QRS3Q2

Date:

01/11/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100321917 SKK9882Z

Claimant Vehicle No:

SHB747Z 15/11/2020 Insured Vehicle No:
Nature of Claim:

TP

Claim No:

2275572347SG

JTDKN36U405768377

2ZR6606051

315747 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB747Z

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Reg. Date: 27/07/2016 (Man. Year: 2015)

Colour: Maroon Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

ring (Serviceable):

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

100

CONDITION OF TYRES

Front Left Side:

Front Right Side:

Front Tyre Size: 195

195/65R15 Sailun 6 mm Sailun 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 195/65R15 Sailun 6 mm

Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,804.94	98.93	7,706.01	98.73
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,050.00	850.00	2,200.00	72.13
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,854.94	948.93	9,906.01	91.26
	Approved Total (Overridden) (S\$)		950.00		

Nett Amount (S\$)	10,854.94	950.00	9,904.94	91.25
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.	.0 x S\$103.26/day) (S\$)	309.78		
	+ Doc/Search Fee (S\$)	7.00		
	+ Other Costs (S\$)	180.00		
	Nett Liability (S\$)	1,596.78		
Global Sum Settlement (S\$)		1,590.00		

INSPECTION

Date of Assignment: 18/11/2020

SMRT Automotive Services Pte Ltd (Woodlands) Date Inspected: Inspected At: 18/11/2020

60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 3.0 days

OI SUN PIN Manager: Adjuster: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

1 1 *NAME PLATE (HYBRID) (DISC 25%) Necessary 2 1 *STICKER DECAL SMRT (DOOR) (SN) Necessary 3 1 *BUMPER FRT Repair 4 1 *FENDER FRT/LH Repair 5 1 *DOOR FRT/LH Repair 6 1 *SOLAR FILM Not Necessary 7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable	51.90 F 60.00 F 482.00 F 723.40 F 894.40 F 125.00 F	*38.93 F *60.00 F *- F *- F
3 1 *BUMPER FRT Repair 4 1 *FENDER FRT/LH Repair 5 1 *DOOR FRT/LH Repair 6 1 *SOLAR FILM Not Necessary 7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable	482.00 F 723.40 F 894.40 F 125.00 F	*-F *-F *-F
4 1 *FENDER FRT/LH Repair 5 1 *DOOR FRT/LH Repair 6 1 *SOLAR FILM Not Necessary 7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable	723.40 F 894.40 F 125.00 F	*-F
5 1 *DOOR FRT/LH Repair 6 1 *SOLAR FILM Not Necessary 7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable	894.40 F 125.00 F	*- F
6 1 *SOLAR FILM Not Necessary 7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable	125.00 F	
7 1 *BUMPER SUPPORT F/LH Serviceable 8 1 *HEAD LAMP LH Serviceable		. .
8 1 *HEAD LAMP LH Serviceable		*- F
	76.40 F	*- F
	945.20 F	*- F
9 1 *FENDER LINER FRT/LH Serviceable	171.70 F	*- F
10 1 *TYRE Serviceable	126.74 F	*- F
11 1 *WHEEL DISC ,FRONT Serviceable	1,484.20 F	*- F
12 1 *QUARTER GLASS FRT /LH Serviceable	234.90 F	*- F
13 1 *SEALANT W/SCREEN Serviceable	37.00 F	*- F
14 1 *MIRROR ASSY ,LH Serviceable	1,224.90 F	*- F
15 1 *MIRROR LAMP LH Serviceable	65.30 F	*- F
16 1 *COVER OUTER MIRROR ,LH Serviceable	107.40 F	*- F
17 1 *MOULDING BODY ,LH Serviceable	673.60 F	*- F
18 1 *HINGE LOWER LHF DOOR Serviceable	90.10 F	*- F
19 1 *HINGE UPPER LHF DOOR Serviceable	80.50 F	*- F
20 1 *CHECK ASSY ,FR DOOR Serviceable	150.30 F	*- F
F=Franchise part.		
Total Parts (S\$	7,804.94	98.93

Report was unsubmitted during this print-out.

11/1/21, 10:52 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	1,674.00	600.00
3	TP CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS	New	120.00	0.00
		Gross Labour Cost (S\$)	3,050.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >