

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20012827/DVD3Q2**Date:** 07/12/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00009882001

Claimant Vehicle No : GBB5549S **Insured Vehicle No :** GBJ2151H

Date of Loss: 18/11/2020 Nature of Claim: TP Claim No: SNM20D204472/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB5549S**
 Make & Model: TOYOTA HIACE, 3.0 TURBO 4DR AT (A) Engine No: 1KD2830744
 Reg. Date: 15/01/2019 (Man. Year: 2018) Chassis No: JTFHT02P600246899
 Colour: Silver Odometer: 81775 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,928.84	3,565.05	11,363.79	76.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	1,710.00	3,020.00	63.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,658.84	5,275.05	14,383.79	73.17
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	19,658.84	4,200.00	15,458.84	78.64
+ GST 7.00/7.00% (S\$)	1,376.12	294.00	1,082.12	78.64
Nett Amount (S\$)	21,034.96	4,494.00	16,540.96	78.64

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 23/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 TURBO 4DR AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5549S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,850.39 FL	*1,850.39 FL
2	1		*TAILGATE LOGO	Necessary	65.29 FL	*65.29 FL
3	1		*TAILGATE INNER BOARD	Not Necessary	441.92 FL	*- FL
4	1		*SET TAILGATE INNER BOARD CLIPS	Not Necessary	20.00 FL	*- FL
5	1		*TAILGATE INNER BOARD HANDLE	Not Necessary	197.00 FL	*- FL
6	1		*TAILGATE CENTER MOULDING	Cut/Mounting Broken	198.00 FL	*198.00 FL
7	1		*SET TAILGATE CENTER MOULDING CLIPS	Not Necessary	20.00 FL	*- FL
8	1		*TAILGATE WEATHER STRIP	Not Necessary	395.00 FL	*- FL
9	1		*TAILGATE INNER LOCK	Bent	340.00 FL	*249.60 FL
10	1		*TAILGATE LOWER LOCK	Not Necessary	105.00 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	288.21 FL	*288.21 FL
12	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	118.00 FL	*- FL
13	1		*TAILGATE THIRD BRAKE LAMP	Not Necessary	385.00 FL	*- FL
14	1		*TAIL LAMP L+R	O/s Cracked/N/s Not Necessary	964.78 FL	*385.50 FL
15	1		*SET TAIL LAMP CLIPS	Not Necessary	20.00 FL	*- FL
16	2		*TAIL LAMP PANEL L+R	Not Necessary	1,178.40 FL	*- FL
17	2		*TAIL LAMP LOWER GARNISH L+R	Not Necessary	479.60 FL	*- FL
18	2		*TAIL LAMP LOWER GARNISH BRACKET L+R	Not Necessary	210.56 FL	*- FL
19	1		*REAR BUMPER	Distorted	612.00 FL	*498.50 FL
20	1		*SET REAR BUMPER CLIPS	Not Necessary	20.00 FL	*- FL
21	1		*REAR BUMPER CENTER BEAM	Not Necessary	398.00 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	116.58 FL	*- FL
23	1		*REAR END PANEL INNER	Repair	933.00 FL	*- FL
24	1		*REAR END PANEL OUTER	Dented	982.00 FL	*691.25 FL
25	1		*REAR FLOOR PANEL EXTENSION	Not Necessary	1,892.39 FL	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,419.00 FL	*- FL
27	1		*REAR FLOOR PANEL MAT	Not Necessary	1,359.00 FL	*- FL
28	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	380.00 FL	*- FL
29	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	60.00 FL	*- FL
30	1		*REAR EXHAUST PIPE	Not Necessary	1,410.00 FL	*- FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
32	1		*REAR EXHAUST BRACKET	Not Necessary	90.00 FL	*- FL
33	1		*REAR NUMBER PLATE	Not Necessary	160.00 FS	*- FS
34	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
35	1		*REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
38	1		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
41	1		*TOYOTA STICKER	Necessary	100.00 FS	*15.00 FS
42	1		*HIACE STICKER	Necessary	100.00 FS	*20.00 FS
43	1		*70KM STICKER	Necessary	100.00 FS	*30.00 FS
44	1		*8PAX STICKER	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,195.12	4,621.74
- List Item Discount on L Items 25.00/25.00% (S\$)	4,266.28	1,056.69
Total Parts (S\$)	14,928.84	3,565.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	New	300.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	700.00
3	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	New	1,600.00	600.00
4	TO TUFF COAT AFFECTED AREAS	New	250.00	40.00
5	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	New	80.00	40.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
Gross Labour Cost (\$\$)			4,730.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >