

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20012828/UQF3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : GBH1876S

Insured Vehicle No : XD3392T

Date of Loss: 20/11/2020

Nature of Claim: TP

Claim No: CDMFG20001715

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH1876S**

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KD2652798

Reg. Date: 26/02/2018 (Man. Year: 2016)

Chassis No: KDY2318026902

Colour: Silver

Odometer: 72113 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15

Rear Tyre Size: 155 R13 (D)

Front Left Side: Linglong 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Linglong 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,774.40	4,533.02	10,241.38	69.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,200.00	1,770.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,744.40	6,733.02	12,011.38	64.08
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	18,744.40	5,300.00	13,444.40	71.72

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 23/11/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-53

Singapore 417808

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Dec 2020)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1876S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,945.20 FL	*1,415.10 FL
2	1		*REAR TAILGATE LOCK LATCH	Bent	278.60 FL	*255.20 FL
3	1		*RH SIDE GATE LOWER MEMBER	Distorted	749.80 FL	*722.10 FL
4	1		*REAR TAILGATE SIDE MEMBER RUBBER RH	Torn	268.50 FL	*151.00 FL
5	1		*REAR TAILGATE SAFETY LOCK RH	Bent	197.60 FL	*197.60 FL
6	4		*REAR TAILGATE HINGES	Not Necessary	544.00 FL	*- FL
7	1		*REAR RH SIDE GATE	Badly Dented	2,876.20 FL	*2,201.20 FL
8	1		*REAR RH SIDE GATE FRONT LATCH	Not Necessary	296.40 FL	*- FL
9	1		*TAILLAMP RH	Cracked	585.40 FL	*208.50 FL
10	1		*TAILLAMPS BRACKET RH	Repair	175.80 FL	*- FL
11	1		*FRONT CABIN REAR CORNER PANEL	Repair	980.50 FL	*- FL
12	1		*FRONT CABIN REAR CENTRE PANEL	Repair	1,486.20 FL	*- FL
13	1		*REAR NUMBER PLATE BRACKET	Not Necessary	155.00 FL	*- FL
14	1		*SET REAR NUMBER PLATE LAMP	Not Necessary	175.00 FL	*- FL
15	1		*REAR TYRE CARRIER	Not Necessary	385.00 FL	*- FL
16	1		*REAR DYNA STICKER	Not Necessary	70.00 FS	*- FS
17	1		*70KM/H STICKER & 13 PAX	Necessary	35.00 FS	*20.00 FS
18	1		*REAR CABIN CANOPY FRAME RH	Not Necessary	1,950.00 FS	*- FS
19	1		*REAR CABIN TOP ALUMINIUM COVER	Distorted	2,500.00 FS	*600.00 FS
20	1		*REAR CABIN TOP ALUMINIUM COVER RIVETS	Necessary	150.00 FS	*50.00 FS
21	1		*REAR CABIN CANOPY COVER RH (KIV)	Torn	680.00 FS	*- FS
22	1		*REAR SIDE GATE RH RAILING	Not Necessary	750.00 FS	*- FS
23	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
24	1		*REAR NUMBER PLATE (CRACKED)	Not Consistent With The Impact	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,549.20	5,820.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,774.80	1,287.68
Total Parts (\$\$)	14,774.40	4,533.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,600.00	1,000.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO REMOVE & INSTALL REAR CABIN BED	New	600.00	300.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
5	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	0.00
6	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (\$\$)			3,970.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >