



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8645L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT FENDER RH	DENTED	761.50	761.50
1	FRT FENDER COWLING RH	TORN	236.70	236.70
1	FRT FENDER "VVTI" EMBLEM RH	NECESSARY	44.30	44.30
1	HEADLAMP RH	CRACKED	2,223.20	2,223.20
1	HEADLAMP BRACKET RH	CRACKED	38.20	38.20
1	FRT BUMPER	DISTORTED	458.90	458.90
1	FRT BUMPER REINFORCEMENT	BENT	379.20	379.20
1	FRT BUMPER SPONGE	CRACKED	109.60	109.60
2	FRT BUMPER BRACKETS	NOT NECESSARY	138.20	-
1	FRT BUMPER RETAINER RH	NECESSARY	62.90	62.90
1	FRT FOG LAMP RH	CRACKED	278.10	278.10
1	FRT FOG LAMP COVER RH	CRACKED	93.80	93.80
1	FRT BUMPER GRILLE	CRACKED	169.70	169.70
1	FRT GRILLE	CRACKED	559.60	559.60
1	FRT GRILLE EMBLEM	NECESSARY	69.40	69.40
1	FRT GRILLE RUBBER	NOT NECESSARY	76.20	-
1	FRT WIPER TANK	DEFORMED	170.40	170.40
1	FRT WIPER TANK MOTOR	NOT NECESSARY	228.70	-
1	RADIATOR UNDER COVER	TORN	185.80	185.80
	LESS 25% DISCOUNT		-1,571.10	-1,460.33
			4,713.30	4,380.97
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT FENDER COWLING CLIPS RH (SN)	NECESSARY	40.00	30.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRT BUMPER GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET FRT GRILLE TOP COVER CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET RADIATOR UNDER COVER CLIPS (SN)	NECESSARY	40.00	20.00
			220.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS.		1,000.00	600.00
	TO SPRAY PAINTING.		1,000.00	800.00
	TO SPRAY UNDERSEAL.		80.00	30.00
	TO CHECK WIRING.		50.00	30.00
			2,130.00	1,460.00
	GRAND TOTAL		7,063.30	5,920.97
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/AGI20012830/Acd3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.