

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012834/DSD3E2

Date: 28/05/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001408792

Claimant Vehicle No : SHD7113X

Insured Vehicle No : SLQ2461H

Date of Loss: 19/11/2020

Nature of Claim: TP

Claim No: 250003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD7113X

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU674648

Reg. Date: 10/11/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU096230

Colour: Blue

Odometer: 393158 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,826.16	10,724.84	10,101.32	48.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	1,830.00	2,860.00	60.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,516.16	12,554.84	12,961.32	50.80
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	25,516.16	10,000.00	15,516.16	60.81
+ GST 7.00/7.00% (S\$)	1,786.13	700.00	1,086.13	60.81
Nett Amount (S\$)	27,302.29	10,700.00	16,602.29	60.81

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate

Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD7113X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Bent	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	35.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Not Necessary	35.70 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Not Necessary	253.40 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
6	10		*BONNET INSULATOR CLIP	Not Necessary	36.80 FL	*- FL
7	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
8	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
9	1		*RADIATOR GRILLE	Not Necessary	1,480.00 FL	*- FL
10	1		*FRONT BUMPER COVER	Dented	1,052.20 FL	*1,052.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	*- FL
12	1		*FRONT BUMPER GRILLE (RH)	Not Necessary	149.20 FL	*- FL
13	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
14	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	98.40 FL	*- FL
15	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	*- FL
16	1		*FRONT BUMPER GRILLE AIR DUCT (RH)	Not Necessary	126.20 FL	*- FL
17	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
18	2		*HEADLAMP (LH/RH)	Mtg Broken	5,552.00 FL	*2,776.00 FL
19	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
20	1		*FRONT FENDER (RH)	Dented	566.30 FL	*566.30 FL
21	1		*FRONT FENDER SHIELD (RH)	Deformed / Torn	174.90 FL	*174.90 FL
22	1		*FRONT WHEEL RIM (RH)	Bent / Dented	650.60 FL	*325.30 FL
23	1		*KNUCKLE ARM (RH)	Distorted	595.90 FL	*595.90 FL
24	1		*FRONT WHEEL BEARING HUB ASSY (RH)	Damaged	673.20 FL	*540.50 FL
25	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	1,104.00 FL	*595.80 FL
26	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	217.60 FL	*- FL
27	1		*STG TIE ROD (RH)	Distorted	186.40 FL	*186.40 FL
28	1		*STG TIE END (RH)	Distorted	125.20 FL	*125.20 FL
29	1		*STABILIZER BAR ASSY	Not Necessary	463.70 FL	*- FL
30	1		*STABILIZER BAR LINK (RH)	Not Necessary	68.10 FL	*- FL
31	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
32	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	2,061.60 FL	*- FL
33	1		*RACK & PINION ASSY	Damaged	1,820.00 FL	*969.60 FL
34	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*- FS
35	1		*RADIATOR	Cracked	1,637.20 FL	*792.95 FL
36	1		*FRONT WHEEL CAP (RH)	Cut	214.20 FL	*107.10 FL
37	1		*WIPER CONTAINER ASSY	Deformed	281.60 FL	*281.60 FL
38	1		*RADIATOR EXPANSION TANK	Cracked	163.80 FL	*163.80 FL
39	1		*FRONT FENDER APRON PANEL (RH)	Dented	637.00 FL	*637.00 FL
40	1		*FRONT SHOCK ABSORBER ASSY (RH)	Distorted	684.40 FL	*342.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,978.70	13,406.05
- List Item Discount on L Items 20.00/20.00% (S\$)	5,152.54	2,681.21
Total Parts (S\$)	20,826.16	10,724.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	180.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	60.00
7	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
8	RE-SET FRT ABS SYSTEM }	New	200.00	150.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	0.00
Gross Labour Cost (S\$)			4,690.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >