

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20012843/R1QF3Q2

Date: 29/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900058505

Claimant
Vehicle No : SMB3166X **Insured Vehicle No :** SMJ5347K

Date of Loss: 08/11/2020 Nature of Claim: TP Claim No: 5383497817SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3166X		
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Engine No:	50340280184024
Reg. Date:	04/01/2016 (Man. Year: 2014)	Chassis No:	WMAA22ZZ9F7002781
Colour:	Green	Odometer:	421690 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	390.00	350.00	40.00	10.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	390.00	350.00	40.00	10.26
+ GST 7.00/7.00% (S\$)	27.30	24.50	2.80	10.26
Nett Amount (S\$)	417.30	374.50	42.80	10.26

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 24/11/2020

Inspected At:

SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR N/S/F CORNER BUMPER TOUCH UP PUTTY ON ACCIDENT AREA RESPRAY ACCIDENT AREA	New	390.00	350.00
Gross Labour Cost (\$\$)			390.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >