

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20012848/USF3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29105785QMY
Claimant		
Vehicle No : SLM7775R	Insured Vehicle No :	SJA8043A
Date of Loss: 22/11/2020	Nature of Claim: TP	Claim No: 631199

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM7775R	Engine No:	R16B21601536
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT001209
Reg. Date:	27/03/2017 (Man. Year: 2016)	Odometer:	76845 km
Colour:	Black		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,194.40	1,710.72	11,483.68	87.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,290.00	1,580.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,064.40	4,000.72	13,063.68	76.56
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	17,064.40	3,200.00	13,864.40	81.25
+ GST 7.00/7.00% (\$\$)	1,194.51	224.00	970.51	81.25
Nett Amount (\$\$)	18,258.91	3,424.00	14,834.91	81.25

INSPECTION

Date of Assignment:	26/11/2020	
Date Inspected:	23/11/2020 Inspected At:	Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM7775R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	820.20 F	*- FL
2	1		*BOOTLID OUTER GARNISH	Not Necessary	655.20 F	*- FL
3	2		*BOOTLID HINGES	Not Necessary	332.60 F	*- FL
4	2		*BOOTLID HINGE GARNISHS	Not Necessary	165.00 F	*- FL
5	1		*BOOTLID REAR LOGO	Not Necessary	50.00 F	*- FL
6	1		*BOOTLID CIVIC EMBLEM	Not Necessary	105.00 F	*- FL
7	1		*BOOTLID VTEC EMBLEM	Not Necessary	98.00 F	*- FL
8	1		*BOOTLID INNER LOCK	Serviceable	99.00 F	*- FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	218.00 F	*70.00 FL
10	2		*BOOTLID REFLECTORS	Not Necessary	681.00 F	*- FL
11	1		*BOOTLID TURBO EMBLEM	Not fitted	33.00 F	*- FL
12	1		*BOOTLID INNER TRIM	Not Necessary	295.00 F	*- FL
13	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
14	1		*REAR BUMPER	Distorted	688.00 F	*617.20 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
17	1		*REAR BUMPER LOWER SIDE BLACK GARNISHS	N/s Twisted	170.00 F	*45.00 FL
18	1		*REAR END PANEL	Dented/Bent	380.00 F	*265.70 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	245.00 F	*50.30 FL
20	1		*REAR FLOOR PANEL	Repair	990.10 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	450.00 F	*- FL
22	1		*TAILLAMPS	N/s Cracked	770.20 F	*307.40 FL
23	2		*TAILLAMP PANELS	Repair	490.00 F	*- FL
24	2		*REAR FENDERS	Repair	1,798.20 F	*- FL
25	2		*REAR FENDER INNER TRIMS	Not Necessary	710.20 F	*- FL
26	1		*REAR BUMPER CENTRE BLACK GARNISH	Distorted	311.20 F	*185.30 FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.00 F	*- FL
28	1		*REAR BUMPER REINFORCEMENT	Bent	388.50 F	*180.00 FL
29	1		*BOOTLID SPOILER W/THIRD BRAKE LIGHT	Not Necessary	1,200.00 FS	*- FS
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
34	1		*REAR ANTENNA SENSOR	Cracked	180.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,194.40	2,060.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	350.18
Total Parts (\$\$)	13,194.40	1,710.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHNISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	30.00
7	LABPUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	900.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			3,870.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >