

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012850/KCD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001262728

Claimant
Vehicle No : SJM8865G

Insured Vehicle No : SMM223B

Date of Loss: 05/11/2020

Nature of Claim: TP

Claim No: 249640

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM8865G**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3221972

Reg. Date: 20/01/2009 (Man. Year: 2008)

Chassis No: JTDER12W603001624

Colour: Metallic Silver

Odometer: 98806 km

Engine Capacity: 1794 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: West Lake 8 mm

Rear Left Side:

West Lake 8 mm

Front Right Side: West Lake 8 mm

Rear Right Side:

West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,509.50	416.25	1,093.25	72.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,215.00	2,165.00	64.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,889.50	1,631.25	3,258.25	66.64
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	4,889.50	1,300.00	3,589.50	73.41
+ GST 7.00/7.00% (S\$)	342.27	91.00	251.27	73.41
Nett Amount (S\$)	5,231.77	1,391.00	3,840.77	73.41

INSPECTION

Date of Assignment: 20/11/2020

Date Inspected: 24/11/2020 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector
C, #01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM8865G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Buckled	500.00 F	*500.00 FL
2	10	*REAR BUMPER CLIPS	Necessary	55.00 F	*55.00 FL
3	1	*REAR BUMPER SIDE RETAINER LH (AT RR FENDER)	Serviceable	60.00 F	* - FL
4	1	*REAR BUMPER SIDE RETAINER RH (AT RR FENDER)	Serviceable	60.00 F	* - FL
5	1	*REAR END PANEL	Repair	468.00 F	* - FL
6	1	*REAR END PANEL TRIM	Serviceable	245.00 F	* - FL
7	1	*REAR END PANEL TRIM CLIPS	Not Necessary	5.50 F	* - FL
8	1	*REAR REFLECTOR LH	Serviceable	58.00 F	* - FL
9	1	*REAR REFLECTOR RH	Serviceable	58.00 F	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,509.50	555.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	138.75

Total Parts (S\$)	1,509.50	416.25
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (REAR)	New	1,500.00	400.00
2	PROVIDE SKILL LABOUR TO STICKER WRAP & PAINTING	New	1,500.00	800.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	80.00	15.00
4	PROVIDE SKILL LABOUR TO WHEEL ALIGMMENT	New	150.00	0.00
5	PROVIDE SKILL LABOUR TO CHECK UNDERCARRIAGE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,380.00	1,215.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >