

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012853/T1QF3E2

Date: 23/02/2021

REFERENCE

Insured/Claimant:	ANG SAU SHIUN	Policy No:	1800102704		
Date of Loss:	21/11/2020	Nature of Claim:	OD	Claim No:	7551848716SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW7576U		
Make & Model:	KIA CERATO K3, 1.6 (A)	Engine No:	G4FGJH702736
Reg. Date:	29/08/2018 (Man. Year: 2018)	Chassis No:	KNAF3416MK5012718
Colour:	Red	Odometer:	43503 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,845.20	4,719.20	9,126.00	65.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	3,490.00	2,080.00	37.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,415.20	8,209.20	11,206.00	57.72
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,815.20	7,609.20	11,206.00	59.56
+ GST 7.00/7.00% (S\$)	1,317.06	532.64	784.42	59.56
Nett Amount (S\$)	20,132.26	8,141.84	11,990.42	59.56

INSPECTION

Date of Assignment:	23/11/2020		
Date Inspected:	23/11/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Not Necessary	2,210.00 FL	*- FL
3	1		*LAMP ASSY-HEAD, RH	Not Necessary	2,210.00 FL	*- FL
4	1		*PANEL-FENDER, LH	Bent	430.00 FL	*430.00 FL
5	1		*INSULATOR-FENDER LH	Not Necessary	27.00 FL	*- FL
6	1		*GUARD ASSY-FRONT WHEEL, LH	Missing	95.00 FL	*95.00 FL
7	10		*CLIP	Necessary	10.00 FL	*10.00 FL
8	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
9	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
10	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
11	1		*MOULDING-FRONT BUMPER, LH	Not Necessary	43.00 FL	*- FL
12	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
13	1		*RETAINER-BUMPER SIDE MTG	Not Necessary	1.00 FL	*- FL
14	1		*COVER-FR BUMPER	Cracked	633.00 FL	*633.00 FL
15	4		*GRILLE-FRONT BUMPER	Cut (1pc Only)	1,940.00 FL	*485.00 FL
16	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
17	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
18	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
19	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
20	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
21	1		*PANEL ASSY-UNDER COVER	Cracked	117.00 FL	*117.00 FL
22	12		*CLIP UNDER COVER	Necessary	12.00 FL	*12.00 FL
23	1		*LH FRONT WHEEL ASSY-ALUMINIUM	Dented	926.00 FL	*926.00 FL
24	1		*HUB ASSY-FR WHEEL	Bent	436.00 FL	*436.00 FL
25	1		*COVER-FR BRAKE DISC DUST LH	Not Necessary	29.00 FL	*- FL
26	1		*KNUCKLE-FRONT AXLE, LH	Bent	350.00 FL	*350.00 FL
27	1		*GEAR ASSY-STEERING	Bent	770.00 FL	*770.00 FL
28	1		*LH LINK-STABILIZER	Bent	72.00 FL	*72.00 FL
29	1		*RH LINK-STABILIZER	Not Necessary	72.00 FL	*- FL
30	1		*STRUT ASSY-FR, LH	Bent	280.00 FL	*280.00 FL
31	1		*STRUT ASSY-FR, RH	Not Necessary	280.00 FL	*- FL
32	1		*BEARING-STRUT	Not Necessary	86.00 FL	*- FL
33	1		*BEARING-STRUT	Not Necessary	86.00 FL	*- FL
34	1		*INSULATOR ASSY-STRUT	Not Necessary	85.00 FL	*- FL
35	1		*INSULATOR ASSY-STRUT	Not Necessary	85.00 FL	*- FL
36	1		*CROSSMEMBER COMPL	Not Necessary	1,156.00 FL	*- FL
37	1		*ARM COMPLETE-FR LWR, LH	Bent	286.00 FL	*286.00 FL
38	1		*ARM COMPLETE-FR LWR, RH	Not Necessary	286.00 FL	*- FL
39	1		*STAY LH	Not Necessary	22.00 FL	*- FL
40	1		*STAY RH	Not Necessary	22.00 FL	*- FL
41	1		*TORSION AXLE COMPLETE	Not Necessary	1,031.00 FL	*- FL
42	1		*UNDER COVER	Not Necessary	143.00 FL	*- FL
43	1		*SHOCK ABSORBER ASSY-REAR	Not Necessary	231.00 FL	*- FL
44	1		*SHOCK ABSORBER ASSY-REAR	Not Necessary	231.00 FL	*- FL
45	1		*HUB & BEARING ASSY-RR	Not Necessary	437.00 FL	*- FL
46	1		*LH REAR WHEEL ASSY-ALUMINIUM	Dented	926.00 FL	*926.00 FL
47	1		*AIR DUCT-FR BUMPER, LH	Deformed	14.00 FL	*14.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,294.00	5,894.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,448.80	1,174.80

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					13,845.20	4,719.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON LH FRONT FENDER, FRONT BUMPER, REPAIR LH FRONT DOOR PANEL, REPAIR REAR BUMPER.	New	1,200.00	800.00
2	REMOVE AND INSTALL PARKING ASSIST FOR FRONT.	New	60.00	60.00
3	REMOVE AND INSTALL PARKING ASSIST FOR REAR.	New	60.00	-
4	PAINT WORK SPARY FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, REAR BUMPER AND AFFECTED PORTION.	New	2,400.00	1,440.00
5	PERFORM RUST PREVENTION.	New	80.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.	New	120.00	120.00
9	SUPPLY LH FRONT TIRE & LH REAR TIRE.	New	840.00	420.00
10	LABOUR RENEW BOTH LH SPORT RIM INCLDING BALANCING.	New	60.00	60.00
11	RENEW FRONT AND REAR UNDERCARRIAGE DAMAGES.	New	600.00	400.00
Gross Labour Cost (\$\$)			5,570.00	3,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >