

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012858/AQF3E2

Date: 17/03/2021

REFERENCE

Insured/Claimant:	GAN WAI SENG	Policy No:	2070054898		
Date of Loss:	17/11/2020	Nature of Claim:	OD	Claim No:	0594876912SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDL186L		
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZD891580
Reg. Date:	25/03/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF31L1077314
Colour:	Black	Odometer:	3686 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,817.00	2,893.76	3,923.24	57.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,652.00	2,722.00	4,930.00	64.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,469.00	5,615.76	8,853.24	61.19
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	13,669.00	4,815.76	8,853.24	64.77
+ GST 7.00/7.00% (S\$)	956.83	337.10	619.73	64.77
Nett Amount (S\$)	14,625.83	5,152.86	9,472.97	64.77

INSPECTION

Date of Assignment:	23/11/2020		
Date Inspected:	23/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Repair	1,271.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
3	1		*FRONT FENDER BRACE - LH	Not Necessary	87.00 FS	*- FS
4	1		*FRONT FENDER BRACKET - LH	Not Necessary	31.00 FS	*- FS
5	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
6	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
7	2		*FRONT WHEEL COVER - LH/RH	Necessary	1,060.00 FS	*424.00 FS
8	1		*FRONT DOOR - LH	Dented	2,553.00 FS	*2,042.40 FS
9	1		*FRONT DOOR OUTER SEAL - LH	Necessary	164.00 FS	*131.20 FS
10	1		*FRONT DOOR CATCH	Not Necessary	119.00 FS	*- FS
11	1		*DOOR HINGE HALVES - LH UPPER	Not Necessary	45.00 FS	*- FS
12	1		*DOOR HINGE HALVES - LH UPPER	Not Necessary	45.00 FS	*- FS
13	1		*DOOR HINGE HALVES - LH LOWER	Not Necessary	45.00 FS	*- FS
14	1		*DOOR HINGE HALVES - LH LOWER	Not Necessary	45.00 FS	*- FS
15	1		*FRONT DOOR COVER - LH	Cut	366.00 FS	*292.80 FS
16	1		*SILL MEMBER TRIM - LH	Not Necessary	177.00 FS	*- FS
17	1		*B PILLAR TRIM - LH	Not Necessary	110.00 FS	*- FS
18	1		*SUNDRIES	Necessary	300.00 FS	*3.36 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,817.00 2,893.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOE HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	280.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS AND LHS FRONT DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REOMVED.	New	3,200.00	750.00
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	New	3,500.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			7,652.00	2,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >