

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012864/KGS3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100396324

Claimant
Vehicle No : SMG6120G **Insured Vehicle No :** SKQ9048J

Date of Loss: 20/11/2020 Nature of Claim: TP Claim No: 7676428829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SMG6120G | | |
| Make & Model: | RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A) | Engine No: | K9KF649D059435 |
| Reg. Date: | 26/12/2018 (Man. Year: 2018) | Chassis No: | VF1RFA00461978014 |
| Colour: | Metallic Brown | Odometer: | 155098 km |
| Engine Capacity: | 1461 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/55R20 | Rear Tyre Size: | 195/55R20 |
| Front Left Side: | Tourador 7 mm | Rear Left Side: | Goodyear 7 mm |
| Front Right Side: | Tourador 7 mm | Rear Right Side: | Goodyear 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 22,512.92 | 14,177.63 | 8,335.29 | 37.02 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,950.00 | 3,080.00 | 1,870.00 | 37.78 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 27,462.92 | 17,257.63 | 10,205.29 | 37.16 |
| Approved Total (Overridden) (S\$) | | 13,500.00 | | |
| (S\$) | 27,462.92 | 13,500.00 | 13,962.92 | 50.84 |
| + GST 7.00/7.00% (S\$) | 1,922.40 | 945.00 | 977.40 | 50.84 |
| Nett Amount (S\$) | 29,385.32 | 14,445.00 | 14,940.32 | 50.84 |
| + Car Rental (14.0 x S\$92.00/day) (S\$) | | 1,288.00 | | |
| Nett Liability (S\$) | | 15,733.00 | | |

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At:

Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #02-02/03 Carros
Centre
Singapore 737869

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------------|-------------|--------------|
| 1 | 1 | | *TAIL LIGHT -INNER RH | Cut | 548.88 FL | *548.88 FL |
| 2 | 1 | | *TAIL LIGHT -INNER LH | Serviceable | 548.88 FL | *- FL |
| 3 | 1 | | *STRIKER ,TRUNK DOOR | Repair | 96.72 FL | *- FL |
| 4 | 1 | | *LOCK ,TRUNK DOOR | Repair | 121.56 FL | *- FL |
| 5 | 1 | | *TAILGATE ASSY | Repair | 2,247.72 FL | *- FL |
| 6 | 1 | | *SEAL ,TRUNK DOOR | Deformed | 197.40 FL | *197.40 FL |
| 7 | 1 | | *TAILGATE PANEL | Cracked | 750.52 FL | *750.52 FL |
| 8 | 1 | | *TAILGATE PANEL STRIP | Dented / Warped | 413.40 FL | *413.40 FL |
| 9 | 6 | | *RIVET | Necessary | 55.44 FL | *55.44 FL |
| 10 | 1 | | *EMBLEM DIAMOND | Necessary | 189.40 FL | *189.40 FL |
| 11 | 1 | | *LETTERING RENAULT | Necessary | 129.60 FL | *129.60 FL |
| 12 | 1 | | *LETTERING SCENIC | Necessary | 151.44 FL | *151.44 FL |
| 13 | 1 | | *REVERSE CAMERA | Not Necessary | 707.88 FL | *- FL |
| 14 | 4 | | *REVERSE SENSOR | Shorted | 1,021.44 FL | *1,021.44 FL |
| 15 | 1 | | *REAR BUMPER | Cracked | 1,152.96 FL | *1,152.96 FL |
| 16 | 1 | | *REAR LOWER BUMPER | Bent | 492.78 FL | *492.78 FL |
| 17 | 1 | | *REAR LOWER BUMPER SILVER | Cracked | 696.24 FL | *696.24 FL |
| 18 | 1 | | *BUMPER BRACKET ,LOWER LH | Cracked | 113.88 FL | *113.88 FL |
| 19 | 1 | | *BUMPER BRACKET ,LOWER RH | Cracked | 113.88 FL | *113.88 FL |
| 20 | 1 | | *BUMPER BRACKET ,CENTER | Cracked | 357.84 FL | *357.84 FL |
| 21 | 10 | | *RIVET ,ALUMINIUM | Necessary | 10.00 FL | *10.00 FL |
| 22 | 1 | | *BUMPER BEAM | Bent | 685.68 FL | *685.68 FL |
| 23 | 1 | | *REAR END PANEL ,OUTER | Bent | 933.12 FL | *933.12 FL |
| 24 | 1 | | *REAR END PANEL ,INNER | Bent | 421.92 FL | *421.92 FL |
| 25 | 1 | | *REAR FLOOR PANEL | Cracked | 1,282.44 FL | *1,282.44 FL |
| 26 | 1 | | *HEAT SHIELD ,MUFFLER | Bent | 259.20 FL | *259.20 FL |
| 27 | 1 | | *TRUNK CARPET | Serviceable | 632.04 FL | *- FL |
| 28 | 1 | | *TAILLAMP OUTER LH | Serviceable | 548.88 FL | *- FL |
| 29 | 1 | | *TAILLAMP OUTER RH | Serviceable | 548.88 FL | *- FL |
| 30 | 2 | | *BUMPER PAD SUPPORT | Cracked | 174.72 FL | *174.72 FL |
| 31 | 1 | | *REAR FOLAMP RH | Serviceable | 256.20 FL | *- FL |
| 32 | 1 | | *REAR FOLAMP LH | Serviceable | 256.20 FL | *- FL |
| 33 | 1 | | *ANTENNA ,KEYLESS ENTRY | Cracked | 105.00 FL | *48.00 FL |
| 34 | 1 | | *BONNET | Buckled | 1,449.00 FL | *1,449.00 FL |
| 35 | 1 | | *FRONT BUMPER | Distorted / Buckled | 1,461.72 FL | *1,461.72 FL |
| 36 | 1 | | *HEADLAMP RH | Mtg Cracked | 1,016.10 FL | *1,016.10 FL |
| 37 | 1 | | *RADIATOR GRILLE | Serviceable | 270.96 FL | *- FL |
| 38 | 1 | | *FENDER ,RH | Repair | 747.12 FL | *- FL |
| 39 | 1 | | *HEADLIGHT SUPPORT BRACKET | Serviceable | 87.00 FL | *- FL |
| 40 | 1 | | *FRONT BUMPER SUPPORT BRACKET | Serviceable | 123.84 FL | *- FL |
| 41 | 1 | | *STORAGE REAR BOARD TRIM GS4 M4S | Mtg Cracked | 284.76 FL | *284.76 FL |
| 42 | 1 | | *EXHAUST PIPE REAR SILENCER GS4 | Bent | 781.68 FL | *781.68 FL |
| 43 | 3 | | *EXHAUST CLAMP X50 M4 S4 2.0 TS | Serviceable | 204.12 FL | *- FL |
| 44 | 1 | | *EXHAUST RR END MOUNTING M4S | Serviceable | 52.56 FL | *- FL |
| 45 | 1 | | *EXHAUST PIPE CENTER GS4 | Serviceable | 279.00 FL | *- FL |
| 46 | 1 | | *EXHAUST PIPE EGR FLAP ASSY GS4 GS3 | Serviceable | 970.44 FL | *- FL |
| 47 | 1 | | *HEAT SHIELD OUTER GS4 BASE | Serviceable | 258.24 FL | *- FL |
| 48 | 1 | | *BUMPER HARNESS REAR GS4 | Torn | 224.40 FL | *224.40 FL |
| 49 | 1 | | *BUMPER RR RH UNDER COVER GS4 | Serviceable | 235.08 FL | *- FL |
| 50 | 1 | | *BUMPER RR LH UNDER COVER GS4 | Cracked | 235.08 FL | *235.08 FL |
| 51 | 2 | | *LICENSE PLATE WITH HOLDER | Bent | 100.00 FS | *90.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **25,003.24** **15,742.92**

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|-------------|-----------|------------------|------------------|
| - List Item Discount on L Items 10.00/10.00% (S\$) | | | | | 2,490.32 | 1,565.29 |
| Total Parts (S\$) | | | | | 22,512.92 | 14,177.63 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | REPLACING FRONT BUMPER ,BONNET ,RH HEADLIGHT AND RH FENDER INCLUDING PANEL BEATING FOR FRONT AFFECTED AREA | New | 500.00 | 400.00 |
| 2 | ADJUST HEADLIGHT FOCUS | New | 50.00 | 20.00 |
| 3 | REPLACING REAR END PANELS AND LOWER PANEL INCLUDING PANEL BEATING FOR REAR AFFECTED AREA } | New | 1,000.00 | 1,000.00 |
| 4 | REPLACING TAILGATE COVER ,REAR BUMPER ,LIGHTING AND DAMAGED BRACKETS } | New | 400.00 | 0.00 |
| 5 | REPLACING EXHAUST MUFFLER ,EXHAUST PIPES AND HEAT SHIELDS | New | 400.00 | 120.00 |
| 6 | SPRAY PAINTING FOR REAR BUMPER ,TAILGATE PANEL ,TAILGATE PANEL STRIP | New | 1,200.00 | 880.00 |
| 7 | SPRAY PAINTING FOR FRONT BUMPER ,BONNET ,RH FENDER AND RADIATOR GRILLE MOULDING | New | 1,400.00 | 660.00 |
| Gross Labour Cost (S\$) | | | 4,950.00 | 3,080.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >