

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012869/UTF3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00001962000
Claimant Vehicle No :	SMM5530G	Insured Vehicle No :	SMK3564H
Date of Loss:	15/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204492/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5530G		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B25510686
Reg. Date:	03/07/2019 (Man. Year: 2019)	Chassis No:	MRHFC5650KT000651
Colour:	Black	Odometer:	21815 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,913.60	1,766.56	8,147.04	82.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,490.00	1,780.00	54.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,183.60	3,256.56	9,927.04	75.30
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	13,183.60	2,600.00	10,583.60	80.28

INSPECTION

Date of Assignment:	23/11/2020	
Date Inspected:	24/11/2020	Inspected At:
		Zoom Autowerks Pte Ltd (HQ)
		15 Kaki Bukit Road 4, #01-53
		Singapore 417808
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM5530G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID PANEL	Dented/Bent	967.00 FL	*572.10 FL
2	1		*BOOTLID INNER TRIM GARNISH	Not Necessary	356.00 FL	*- FL
3	2		*BOOTLID HINGE	Not Necessary	156.00 FL	*- FL
4	1		*BOOTLID CENTRE GARNISH	Not Necessary	175.00 FL	*- FL
5	1		*BOOTLID LOGO	Necessary	98.00 FL	*13.30 FL
6	1		*BOOTLID EMBLEM (CIVIC)	Necessary	78.60 FL	*25.00 FL
7	1		*BOOTLID EMBLEM (I-VTEC)	Necessary	78.40 FL	*25.00 FL
8	1		*BOOTLID INNER LOCK	Bent	245.00 FL	*81.20 FL
9	1		*BOOTLID LOCK SENSOR	Cracked	186.00 FL	*60.80 FL
10	2		*BOOTLID LAMP	Not Necessary	1,172.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	276.00 FL	*159.20 FL
12	2		*TAILLAMP	Not Necessary	1,572.00 FL	*- FL
13	1		*REAR BUMPER	Dented/Deformed	867.00 FL	*617.20 FL
14	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.00 FL	*- FL
15	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	328.00 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	370.00 FL	*180.00 FL
18	1		*REAR BUMPER PLASTIC LOWER BRACKET	No such part	228.00 FL	*- FL
19	2		*REAR BUMPER TOP BRACKET	Not Necessary	260.00 FL	*- FL
20	1		*REAR BUMPER LOWER GARNISH	Deformed	280.00 FL	*148.00 FL
21	1		*REAR BUMPER KEYLESS SENSOR	Repeated	258.00 FL	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
23	1		*REAR SPARE TYRE TOP GARNISH	Not Necessary	245.00 FL	*- FL
24	1		*REAR SPARE TYRE PANEL	Repair	894.00 FL	*- FL
25	1		*REVERSE SENSOR (4 Pcs)	Shorted (2 Pcs only)	980.00 FL	*296.40 FL
26	1		*SET REVERSE SENSOR HOLDER	Not Necessary	175.00 FL	*- FL
27	1		*REAR BUZZER	Not Necessary	170.00 FL	*- FL
28	1		*REAR END PANEL	Repair	580.00 FL	*- FL
29	1		*REAR END PANEL TOP GARNISH	Not Necessary	195.00 FL	*- FL
30	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
31	1		*BOOTLID SEALANT	Not Necessary	60.00 FS	*- FS
32	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	60.00 FS	*- FS
33	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
34	1		*REAR SPARE TYRE PANEL INSULATOR (ACCESSORIES)	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,222.00 2,208.20
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,308.40 441.64

Total Parts (\$\$) 9,913.60 1,766.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	550.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	700.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR BOOTLID TRIM,GARNISH	New	200.00	60.00
5	TO REMOVE & INSTALL REAR BOOTLID INTERIOR COMPONENTS	New	200.00	80.00
6	TO REMOVE & INSTALL,ALIGN REVERSE SENSOR	New	120.00	50.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			3,270.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >