



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20012873/Uqf3e2	
			Date: 05/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 8338J	Veh. Inspected	SKF 1316X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003391/IJH	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	23/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA GS350 (A)	c.c	3456	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JTHBE1BL705010114	Colour	GREY	
Odometer	117183 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45Z R18	YOKOHAMA	6 mm	
L/H Front Tyre	235/45Z R18	YOKOHAMA	6 mm	
R/H Rear Tyre	235/45Z R18	YOKOHAMA	6 mm	
L/H Rear Tyre	235/45Z R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2020	Inspection Date	24/11/2020	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	