

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20012878/KQF3E2

**Date:** 07/12/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MW009194

**Claimant Vehicle No :** SHD582X

**Insured Vehicle No :** SKW878H

Date of Loss: 19/11/2020

Nature of Claim: TP

Claim No: M2005737

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD582X**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C003403

Reg. Date: 01/03/2017 (Man. Year: 2016)

Chassis No: VF1ABL15AUC283453

Colour: White/Red

Odometer: 500602 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 8 mm

Rear Left Side: Sailun 7 mm

Front Right Side: Sailun 8 mm

Rear Right Side: Sailun 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,081.07	5,378.21	10,702.86	66.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	1,150.00	4,470.00	79.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>21,701.07</b>	<b>6,528.21</b>	<b>15,172.86</b>	<b>69.92</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,200.00</b>		
<b>(\$\$)</b>	21,701.07	5,200.00	16,501.07	76.04
<b>+ GST 7.00/7.00% (\$\$)</b>	1,519.07	364.00	1,155.07	76.04
<b>Nett Amount (\$\$)</b>	<b>23,220.14</b>	<b>5,564.00</b>	<b>17,656.14</b>	<b>76.04</b>

### INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 20/11/2020 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2020)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD582X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER FRT	Buckled / Distorted	747.20 FL	-	*747.20 FL
2	1		*BUMPER BEAM FRT	Repair	663.70 FL	-	*- FL
3	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	-	*- FL
4	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	-	*- FL
5	1		*BUMPER BRACKET FRT LH (HEADLAMP LOWER)	Serviceable	116.47 FL	-	*- FL
6	1		*BUMPER BRACKET FRT RH (HEADLAMP LOWER)	Serviceable	116.47 FL	-	*- FL
7	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	-	*- FL
8	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	-	*101.40 FL
9	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	-	*- FL
10	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	-	*- FL
11	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	-	*- FL
12	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	-	*- FL
13	1		*BONNET LOCK	Distorted	152.80 FL	-	*152.80 FL
14	1		*BONNET HINGE LH	Repair	237.40 FL	-	*- FL
15	1		*BONNET HINGE RH	Repair	237.40 FL	-	*- FL
16	1		*HEADLAMP LH	Mtg Cracked	743.60 FL	-	*743.60 FL
17	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	-	*743.60 FL
18	1		*HEADLAMP PANEL FRT LH	Bent	128.30 FL	-	*128.30 FL
19	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	-	*- FL
20	1		*RADIATOR GRILLE FRAME	Cracked	686.00 FL	-	*686.00 FL
21	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	-	*- FL
22	1		*FRAME FULL SUPPORT BRACKET	Bent	41.60 FL	-	*41.60 FL
23	1		*RADIATOR GRILLE	Missing	969.90 FL	-	*969.90 FL
24	1		*RADIATOR GRILLE BADGE RENAULT	Missing	225.36 FL	-	*225.36 FL
25	1		*HORN	Serviceable	449.90 FL	-	*- FL
26	1		*HORN BRACKET	Serviceable	21.90 FL	-	*- FL
27	1		*A/C CONDENSER	Serviceable	1,537.80 FL	-	*- FL
28	1		*BONNET	Bent	1,312.70 FL	-	*1,312.70 FL
29	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	-	*- FL
30	1		*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	-	*- FL
31	1		*STEERING PUMP ELECTRIC	Serviceable	2,026.70 FL	-	*- FL
32	1		*AUTO COMPUTER	Serviceable	1,287.30 FL	-	*- FL
33	1		*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	-	*- FL
34	1		*SET BUMPER CLIP FRT	Necessary	90.00 FS	-	*66.00 FS
35	1		*BUMPER BRACKET CLIP FRT	Repair	75.00 FS	-	*- FS
36	1		*BUMPER SUPPORT CLIP FRT	Not Necessary	10.00 FS	-	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
37	1		*SET RADIATOR GRILLE SCREW	Not Necessary	55.00 FS	-	*- FS
38	1		*SET RADIATOR GRILLE FRAME CLIP L70Y	Not Necessary	60.00 FS	-	*- FS
39	1		*SET BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	-	*- FS
40	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	-	*- FS
41	1		*BUMPER FOG LAMP GRILLE CLIP	Not Necessary	65.00 FS	-	*- FS
42	1		*BUMPER SPOILER CLIP	Not Necessary	60.00 FS	-	*- FS
43	1		*LICENCE PLATE WITH HOLDER	Dented	80.00 FS	-	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>17,797.30</b>	<b>5,963.46</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,716.23	585.25
<b>Total Parts (\$)</b>	<b>16,081.07</b>	<b>5,378.21</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,800.00	500.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO REMOVE AND REFIT BATTERY, ELECTRICAL WIRING, FUSE BOX AND RELAY TO ENABLE REPAIR	New	450.00	0.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>5,620.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >