Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012882/R1GS3Q2

**Date:** 18/02/2021

**REFERENCE** 

Date of Loss: 14/11/2020 Nature of Claim: TP Claim No: 6228473131SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FV1830C

 Make & Model:
 HONDA ACCORD, 1.6 (M)
 Engine No:
 KR150EEA55321

 Reg. Date:
 09/07/2002 (Man. Year: 2001)
 Chassis No:
 KR150KA55321

 Colour:
 Green
 Odometer:
 64880 km

Engine Capacity: 148 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 80/90-17 Rear Tyre Size: 80/90-17
Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,628.10	909.90	718.20	44.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	305.00	305.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,933.10	1,214.90	718.20	37.15
Approved Total (Overridden) (S\$)		950.00		
(S\$)	1,933.10	950.00	983.10	50.86
+ GST 7.00/7.00% (S\$)	135.32	66.50	68.82	50.86
Nett Amount (S\$)	2,068.42	1,016.50	1,051.92	50.86
Global Sum S	ettlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 23/11/2020

Date Inspected: 24/11/2020 Inspected At: Southern Motor (HQ)

BLK 1006 BUKIT MÉRAH LANE 2,

#01-10

Singapore 159762

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FAIRING	Scratched	285.00 FL	*285.00 FL	
2	1		*FRONT MUDGUARD	Scratched	98.00 FL	*98.00 FL	
3	2		*FRONT SIGNAL RH/LH	Missing	70.00 FL	*70.00 FL	
4	1		*FRONT BRACE DISC	*Check	225.00 FL	*-FL	
5	1		*BRAKE SHOE PUMP	*Check	265.00 FL	*-FL	
6	1		*BRAKE PEDAL	Bent	75.00 FL	*75.00 FL	
7	1		*BRAKE LEVER	Scratched	18.00 FL	*18.00 FL	
8	1		*FRONT FAIRING BRACKET	Bent	185.00 FL	*185.00 FL	
9	1		*HANDLE BAR	Bent	90.00 FL	*90.00 FL	
10	1		*AIR PIPE COVER	*Check	48.00 FL	*- FL	
11	1		*REAR SIDE BOX	Not Necessary	260.00 FL	*-FL	
12	1		*EXHAUST PIPE	Scratched	190.00 FL	*190.00 FL	
F=Fra	nchise	part. L=ListIte	mDisc.	Cub Total (CC)	4 000 00	4.044.00	
				Sub Total (S\$)	<b>1,809.00</b> 180.90	1,011.00	
	- List Item Discount on L Items 10.00/10.00% (S\$)					101.10	
				Total Parts (S\$)	1,628.10	909.90	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TRANSPORT	New	30.00	30.00				
2	ALIGNMENT FORK	New	75.00	75.00				
3	LABOR	New	200.00	200.00				
		Gross Labour Cost (S\$)	305.00	305.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >