

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012885/R1SD3E2

Date: 12/01/2021

REFERENCE

Insured/Claimant:	VEDHARATHNAM RAJAGOPAL	Policy No:	1800055429	
Date of Loss:	22/11/2020	Nature of Claim:	OD	Claim No: 5347871602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA2383Y		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UGR8640
Reg. Date:	31/05/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH001684
Colour:	Grey	Odometer:	29111 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,012.65	4,819.18	1,193.47	19.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,770.00	6,535.00	1,235.00	15.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,782.65	11,354.18	2,428.47	17.62
+ GST 7.00/7.00% (S\$)	964.79	794.79	170.00	17.62
Nett Amount (S\$)	14,747.44	12,148.97	2,598.47	17.62

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL,RR END	Bent	425.00 FL	*425.00 FL
2	1		*TRIM,RR END	Deformed	66.00 FL	*66.00 FL
3	2		*GROMMET,RR END TRIM	Necessary	6.00 FL	*6.00 FL
4	1		*BOARD,TRUNK ROOM FLOOR	Cracked	195.00 FL	*195.00 FL
5	1		*HINGE,TRUNK LID,LH	Serviceable	203.00 FL	*- FL
6	1		*HINGE,TRUNK LID,RH	Serviceable	203.00 FL	*- FL
7	1		*WEATHERSTRIP,TRUNK LID	Serviceable	157.00 FL	*- FL
8	1		*LATCH,TRUNK LID	Serviceable	218.00 FL	*- FL
9	1		*STRIKER,TRUNK LID LATCH	Serviceable	20.00 FL	*- FL
10	1		*PANEL,TRUNK LID	Buckled	791.00 FL	*791.00 FL
11	1		*CHROME GARNISH,RR END PANEL	Cracked	336.00 FL	*336.00 FL
12	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
13	1		*MARK,ATTRAGE	Necessary	21.00 FL	*21.00 FL
14	1		*DUCT,RR VENTILATOR	Cut	30.00 FL	*30.00 FL
15	1		*COVER,RR VENTILATOR	Cut	40.00 FL	*40.00 FL
16	1		*ANT,KEYLESS OPERATION,RR	Serviceable	96.00 FL	*- FL
17	1		*BUZZER,KEYLESS OPERATIO,RR	Cracked	91.00 FL	*91.00 FL
18	1		*LAMP ASSY,COMB,RR LH	Serviceable	335.00 FL	*- FL
19	1		*LAMP ASSY,COMB,RR RH	Cracked	335.00 FL	*335.00 FL
20	2		*GROMMET,TAIL LAMP	Necessary	6.00 FL	*6.00 FL
21	4		*GROMMET,TAIL LAMP	Necessary	12.00 FL	*12.00 FL
22	1		*PANEL,QTR,OTR RH	Buckled	763.00 FL	*763.00 FL
23	1		*PANEL,RR COMB LAMP HSG,RH	Serviceable	60.00 FL	*- FL
24	1		*EXTN,QTR PANEL,UPR OTR RH	Serviceable	118.00 FL	*- FL
25	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
26	3		*SPACER,RR WINDOW	Necessary	27.00 FL	*27.00 FL
27	1		*BRACKET,RR BUMPER,LH	Serviceable	28.00 FL	*- FL
28	1		*BRACKET,RR BUMPER,RH	Serviceable	28.00 FL	*- FL
29	4		*CLIP,RR BUMPER	Necessary	16.00 FL	*16.00 FL
30	1		*FACE,RR BUMPER	Deformed	748.00 FL	*748.00 FL
31	1		*DECAL,MIVEC	Not Necessary	36.00 FL	*- FL
32	1		*ATTRAGE BODYKITS	Cracked	1,643.00 FS	*1,643.00 FS
33	1		*REAR NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
34	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
35	3		*CLIP,GEARSHIFT CONTROL LIN	Not Necessary	9.00 FL	*- FL
36	1		*LAMP ASSY, LICENSE PLATE	Cracked	51.00 FL	*51.00 FL

(Supplementary)

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,288.00	5,747.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,275.35	927.82
Total Parts (\$\$)	6,012.65	4,819.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID,REAR BUMPER,CUT/WELD REAR END PANEL,LH REAR FENDER,REPAIR RH REAR FENDER,REPAIR REAR FLOOR PANEL	New	3,150.00	2,700.00
2	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
3	REMOVE AND INSTALL PARKING SENSOR	New	60.00	60.00
4	REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	240.00	240.00
5	SUPPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
6	PAINT WORK SPRAY REAR FLOOR PANEL,REAR END PANEL,REAR BOOT LID,REAR BUMPER FACE,RH REAR FENDER,LH REAR FENDER,REAR BODY KITS,REAR SPOILER AND AFFECTED PORTION	New	3,150.00	2,625.00
7	SUPPLY PARKING SENSOR	New	220.00	0.00
8	SUPPLY C&C LOGO	New	40.00	40.00
9	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	RE-APPLY ZERTONA COATING ON AFFECTED PORTION	New	320.00	320.00
12	APPLY BODY SEALANT	New	120.00	120.00
13	PERFORM RUST PREVENTION	New	120.00	80.00
Gross Labour Cost (\$\$)			7,770.00	6,535.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >