

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/III20012891/NVD3E2  
**Date:** 05/02/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015		
<b>Claimant Vehicle No :</b>	FBJ969D	<b>Insured Vehicle No :</b>	SH6535S		
Date of Loss:	15/11/2020	Nature of Claim:	TP	Claim No:	MCT20110232

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBJ969D</b>	Engine No:	RC88E6313471
Make & Model:	YAMAHA FZ150, 150cc	Chassis No:	JH2RC95A3KK205878
Reg. Date:	27/11/2019 (Man. Year: 2019)	Odometer:	35072 km
Colour:	Grey		
Engine Capacity:	745 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	160/60 R15
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,486.30	4,946.10	5,540.20	52.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	730.00	1,200.00	62.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,416.30</b>	<b>5,676.10</b>	<b>6,740.20</b>	<b>54.29</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	869.14	397.33	471.81	54.28
<b>Nett Amount (\$\$)</b>	<b>13,285.44</b>	<b>6,073.43</b>	<b>7,212.01</b>	<b>54.29</b>

### INSPECTION

Date of Assignment:	23/11/2020		
Date Inspected:	24/11/2020	Inspected At:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	4.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$4,843.00 NETT)

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 05 Feb 2021)	
<b>Parts:</b>	N/A	YAMAHA FZ150 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBJ969D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Scratched	385.00 FL	*385.00 FL
2	1		*FRONT LEFT FORK ASSY	* Check	1,388.00 FL	*- FL
3	1		*FRONT RIGHT FORK ASSY	* Check	1,388.00 FL	*- FL
4	1		*STEERING STEM	* Check	485.00 FL	*- FL
5	2		*STEERING STEM BEARING	* Check	90.00 FL	*- FL
6	1		*FRONT WHEEL AXLE	Serviceable	188.00 FL	*- FL
7	1		*FRONT BRAKE DISK LEFT	Serviceable	460.00 FL	*- FL
8	1		*FRONT BRAKE DISK RIGHT	Serviceable	460.00 FL	*- FL
9	1		*FRONT WINDSHIELD	Missing	450.00 FL	*450.00 FL
10	4		*WINDSHIELD NUT	Necessary	40.00 FL	*40.00 FL
11	4		*WINDSHIELD SCREW	Necessary	40.00 FL	*40.00 FL
12	2		*FRONT WINDSHIELD COVER	Missing	280.00 FL	*280.00 FL
13	1		*HEAD LIGHT PROTECTOR	Missing	75.00 FL	*75.00 FL
14	1		*FRONT COVER ASSY	Scratched	430.00 FL	*430.00 FL
15	1		*LEFT SIDE SILVER COVER	Scratched	185.00 FL	*185.00 FL
16	1		*LEFT SIDE FAIRING ASSY UPPER	Scratched	550.00 FL	*550.00 FL
17	1		*LEFT SIDE FAIRING BLACK COVER	* Check	295.00 FL	*- FL
18	1		*FOG LAMP	Broken	285.00 FL	*285.00 FL
19	1		*LEFT SIDE CRASH BAR	Deformed	235.00 FL	*235.00 FL
20	1		*STEERING HANDLE	* Check	305.00 FL	*- FL
21	1		*LEFT BRAKE LEVER	Scratched	145.00 FL	*145.00 FL
22	1		*LEFT VIEW MIRROR	Scratched	145.00 FL	*145.00 FL
23	1		*LEFT FRONT SIGNAL ASSY	Scratched	149.00 FL	*149.00 FL
24	1		*LEFT HANDGUARD	Broken	185.00 FL	*185.00 FL
25	1		*LEFT FLOORSTEP	* Check	305.00 FL	*- FL
26	1		*LEFT LOWER COVER	* Check	289.00 FL	*- FL
27	1		*SIDE STAND	* Check	175.00 FL	*- FL
28	1		*LEFT BOX BRACKET	Broken	305.00 FL	*305.00 FL
29	1		*FRONT SPORT RIM	Scratched	885.00 FS	*885.00 FS
30	1		*BOX RACK	* Check	295.00 FS	*- FS
31	1		*TOP CASE	Deformed	480.00 FS	*480.00 FS
32	1		*LEFT BALANCER	Scratched	95.00 FL	*95.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,467.00</b>	<b>5,344.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	980.70	397.90
<b>Total Parts (\$)</b>	<b>10,486.30</b>	<b>4,946.10</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGES (* Check)	New	120.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	450.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	150.00	80.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES (* Check)	New	180.00	0.00
6	SPRAY PAINTING	New	300.00	200.00
Gross Labour Cost (\$\$)			1,930.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >