



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC20012905/T1td3e2

Date: 02-12-2020



ATTN : CHRYLLIS

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 3292Z	Veh. Inspected	GBF 6017H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1110255-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	24/11/2020

2. Vehicle Particulars & Condition

Make & Model	mitsubishi canter	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	FEA01BA20330	Colour	WHITE
Odometer	97633 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	AUSTONE	6 mm
L/H Front Tyre	195 R15	AUSTONE	6 mm
R/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm
L/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/11/2020	Inspect Date / Time	24/11/2020 (03:35 PM)
Survey held at	8 TUAS AVENUE 18 LEVEL 5		
Repairer	VENDA ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------