

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924 INV No. AC2008239

INV Date 10/12/2020

Reference CS/AGI20012911/Usd3q2

Code AGI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SKU 1163R

Insured Veh. SMT 3958H

Claim No. C10008056/ST

Policy No.

Accident Date 20/11/2020

Inspection Date 24/11/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI20012911/Usd3q2

(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date: 10-12-2020



			Code: AGI		
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMT 3958H	Veh. Inspected	SKU 1163R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008056/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	24/11/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA ALPHARD (A)	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JTNGF3DH808000226	Colour	WHITE	
	Odometer	254021	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Conditi	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	235/50 R18	MICHELIN	6 mm	
	L/H Front Tyre	235/50 R18	MICHELIN	6 mm	
	R/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
	L/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				

DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	20/11/2020	Inspection Date	24/11/2020
	Survey held at	vey held at AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933		
Fo Domovico				

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 1163R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED / DISTORTED	1,381.45	1,381.45
1	FRONT BUMPER PDC SENSOR-RH	SHORTED	414.75	414.75
1	FRONT BUMPER FOG LAMP-RH	SERVICEABLE	481.35	-
1	FRONT BUMPER FOG LAMP COVER	TWISTED	121.50	121.50
1	FRONT BUMPER TOW COVER	NOT NECESSARY	58.85	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	180.63	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	501.60	-
2	FRONT BUMPER SIDE RETAINERS-L/R @\$89.55	O/S BENT	179.10	89.55
1	FRONT FENDER-RH	TO REPAIR SEE LABOUR	899.60	-
1	FRONT HEADLAMP-RH	CRACKED	4,249.36	3,606.90
1	FRONT HEADLAMP SIDE MOULDING-RH	NOT NECESSARY	181.93	-
1	FRONT GRILLE ASSY	NOT NECESSARY	1,330.50	-
1	WASHER TANK	NOT NECESSARY	241.60	-
	LESS 25% DISCOUNT		-2,555.55	-1,403.54
			7,666.67	4,210.61
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	FRONT SPORT WHEEL (SN)	NOT NECESSARY	650.00	-
			695.00	45.00
	LABOUR			
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	50.00	_
	TO RESPRAY PAINTING AND ETC.		800.00	450.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER-RH.		800.00	300.00
			1,700.00	770.00
	GRAND TOTAL		10,061.67	5,025.61

Report Ref No. CS/AGI20012911/Usd3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI20012911/Usd3q2

CHUA KANG SENG
Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKU 1163R


### RE-INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKU 1163R

INSPECTION


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

