

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012913/AGS3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993738
Claimant Vehicle No :	SLA3220P	Insured Vehicle No :	GBJ3212J
Date of Loss:	18/11/2020	Nature of Claim:	TP
		Claim No:	0103618119SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA3220P		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4025662
Reg. Date:	26/02/2016 (Man. Year: 2015)	Chassis No:	RU11105659
Colour:	Silver	Odometer:	83970 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,755.12	6,712.88	6,042.24	47.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,390.00	2,070.00	59.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,215.12	8,102.88	8,112.24	50.03
Approved Total (Overridden) (S\$)		6,400.00		

(S\$)	16,215.12	6,400.00	9,815.12	60.53
+ GST 7.00/7.00% (S\$)	1,135.06	448.00	687.06	60.53
Nett Amount (S\$)	17,350.18	6,848.00	10,502.18	60.53
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,555.45		

INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020

Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	976.50 FL	*976.50 FL
2	2		*BONNET CENTER RUBBER	Not Necessary	88.00 FL	*- FL
3	2		*BONNET SIDE RUBBER	Not Necessary	112.00 FL	*- FL
4	1		*BONNET INNER LOCK	Not Necessary	281.00 FL	*- FL
5	2		*BONNET HINGE	Not Necessary	265.40 FL	*- FL
6	2		*HEAD LAMP	Cracked	3,780.00 FL	*3,780.00 FL
7	2		*HEAD LAMP SIDE BRACKET	Not Necessary	150.80 FL	*- FL
8	2		*HEAD LAMP LOWER HOLDER	Cracked	283.00 FL	*283.00 FL
9	1		*FRONT GRILLE	Cracked	375.40 FL	*375.40 FL
10	1		*FRONT GRILLE BADGE	Necessary	67.30 FL	*67.30 FL
11	1		*FRONT GRILLE OUTER PAD	Cut	276.40 FL	*276.40 FL
12	2		*FRONT GRILLE CHROME MOULDING	Cut	153.80 FL	*153.80 FL
13	1		*FRONT GRILLE TOP SUPPORTOR	Cracked	166.80 FL	*166.80 FL
14	1		*FRONT BUMPER	Deformed	489.80 FL	*489.80 FL
15	2		*FRONT BUMPER SIDE RETAINER	Necessary	170.00 FL	*74.00 FL
16	2		*FRONT BUMPER LOWER SIDE BRACKET	Not Necessary	150.00 FL	*- FL
17	1		*FRONT BUMPER TOWING COVER	Not Necessary	57.30 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	625.40 FL	*321.00 FL
19	2		*FRONT BUMPER REINFORCEMENT RUBBER	Not Necessary	144.00 FL	*- FL
20	1		*FRONT BUMPER LOWER GRILLE	Deformed	321.00 FL	*189.00 FL
21	2		*FRONT BUMPER FOG LAMP	Not Necessary	796.00 FL	*- FL
22	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	322.00 FL	*- FL
23	1		*FRONT BUMPER LOWER DIFFUSER	Not Necessary	279.60 FL	*- FL
24	1		*FRONT BUMPER UNDER COVER	Not Necessary	317.00 FL	*- FL
25	1		*FRONT WHEEL ARCH GARNISH	N/S Cracked	779.40 FL	*195.00 FL
26	1		*SUPPORT PANEL	Repair	689.00 FL	*- FL
27	1		*SUPPORT TOP GARNISH	Deformed	244.30 FL	*95.00 FL
28	1		*OUTER TEMPERATURE SENSOR	Not Necessary	398.00 FL	*- FL
29	1		*RADIATOR CAP HEAD	Not Necessary	165.00 FL	*- FL
30	1		*FRONT AIR DUCT	Cracked	172.10 FL	*77.50 FL
31	1		*AIR CON CONDENSER	Bent	658.10 FL	*658.10 FL
32	2		*AIR CON CONDENSER SIDE GUIDE	Not Necessary	125.00 FL	*- FL
33	2		*AIR CON CONDENSER SIDE MOUNTING	Not Necessary	126.40 FL	*- FL
34	1		*RADIATOR	Not Necessary	1,250.60 FL	*- FL
35	1		*SET BONNET CENTER RUBBER CLIP	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET BONNET SIDE RUBBER CLIP	Not Necessary	30.00 FS	*- FS
37	1		*SET HEAD LAMP BULK	Not Necessary	80.00 FS	*- FS
38	1		*SET FRONT GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
39	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
40	1		*FRONT BUMPER FOG LAMP BULK	Not Necessary	30.00 FS	*- FS
41	1		*SET FRONT BUMPER UNDER COVER CLIP	Not Necessary	40.00 FS	*- FS
42	1		*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*SET SUPPORT TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
44	1		*RADIATOR GRILLE	Necessary	50.00 FS	*40.00 FS
45	1		*FRONT NUMBER PLATE WITH BASE	Cracked	80.00 FS	*60.00 FS
					Sub Total (\$\$)	15,806.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	3,051.28
					Total Parts (\$\$)	12,755.12
						6,712.88

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	100.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	40.00
5	REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	New	180.00	60.00
6	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	180.00	60.00
Gross Labour Cost (S\$)			3,460.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >