### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012926/QSD3E2

**Date:** 22/12/2020

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001469539

Claimant Vehicle SMG003G Policy No: CRA58458

No: SMG9093G Insured Vehicle No: GBA5845S

Date of Loss: 23/11/2020 Nature of Claim: TP Claim No: 250079

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMG9093G

 Make & Model:
 HONDA VEZEL, 1.5 1.5X CVT (A)
 Engine No:
 L15B5559817

 Reg. Date:
 03/01/2019 (Man. Year: 2018)
 Chassis No:
 RU11309809

 Colour:
 Black
 Odometer:
 109664 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,118.36	6,403.72	1,714.64	21.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	2,010.00	110.00	5.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,238.36	8,413.72	1,824.64	17.82
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	10,238.36	6,750.00	3,488.36	34.07
+ GST 7.00/7.00% (S\$)	716.69	472.50	244.19	34.07
Nett Amount (S\$)	10,955.05	7,222.50	3,732.55	34.07

**INSPECTION** 

Date of Assignment: 24/11/2020

Af & Cars Pte Ltd (HQ)

Date Inspected: 24/11/2020 Inspected At: 39 Woodlands Close, #01-34/35, Mega @ Woodlands

Singapore 737856

Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN Manager: Hiew May Fung

any other liability under any other circumstances is hereby expressly excluded.	

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2020)

Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG9093G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP L/R	N/S Cracked	3,430.40 FL	*1,715.20 FL
2	1		*FRONT GRILLE BASE	Crumpled	380.20 FL	*380.20 FL
3	1		*FRONT GRILLE CHROME	Crumpled	385.20 FL	*385.20 FL
4	1		*FRONT REINFORCEMENT	Bent	360.80 FL	*360.80 FL
5	1		*FRONT BUMPER	Crumpled	927.50 FL	*815.00 FL
6	1		*FRONT BUMPER LOWER GARNISH	Crumpled	381.20 FL	*381.20 FL
7	1		*REAR BUMPER	Dented	927.50 FL	*876.00 FL
8	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	35.00 FL	*35.00 FL
9	1		*REAR TAILGATE	Dented	1,100.90 FL	*1,100.90 FL
10	1		*REAR TAILGATE MECHANISM LOCK	Jammed	256.90 FL	*182.00 FL
11	1		*REAR TAILGATE WEATHER STRIP	Crumpled	96.80 FL	*96.80 FL
12	2		*REAR TAIL LAMP L/R	Cracked	949.20 FL	*760.00 FL
13	1		*REAR END PANEL	Dented	411.90 FL	*411.90 FL
14	1		*REAR END PANEL TOP GARNISH COVER	Crumpled	98.20 FL	*98.20 FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
16	1		*REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*SET FRONT BUMPER NO. PLATE	Crumpled	35.00 FS	*35.00 FS
18	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Crumpled	60.00 FS	*60.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	10,066.70	7,923.40
			- List Item Discount on L Ite	ms 20.00/20.00% (S\$)	1,948.34	1,519.68
				Total Parts (S\$)	8.118.36	6.403.72

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			,
1	TO REMOVE, REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	100.00	30.00
2	TO REMOVE / REINSTALL REAR WINDSCREEN (TO FR)	New	120.00	120.00
3	TO TRANSFER TAILGATE / BOOTLID MECHANISM AND WIRING ASSY (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	800.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	1,000.00
	Gross Labou	ır Cost (S\$)	2,120.00	2,010.00
	Report was unsubmitted during this p	rint-out.		

< END OF ESTIMATES >