Adjuster Report Page 1 of 4

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012927/APA3Q2

Date: 14/04/2021

**REFERENCE** 

India International Insurance Handling Insurer:

Pte Ltd

Policy No: D18MPC0000315\_02

Claimant Vehicle No:

SJP6539X

**Insured Vehicle** No:

SJR9125B

Date of Loss: 19/11/2020 Nature of Claim: TP Claim No:

MPC2020D0002487

R16A14002931

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SJP6539X Reg No:

Make & Model: HONDA CIVIC, 1.6 5AT (A) Engine No:

31/03/2009 (Man. Year: 2008) Reg. Date: Chassis No: JHMFD46209S200763

Colour: Odometer: Grey 186049 km

**Engine Capacity:** 1595 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,645.70	1,586.88	3,058.82	65.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	630.00	1,770.00	73.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,045.70	2,216.88	4,828.82	68.54
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	7,045.70	1,700.00	5,345.70	75.87
+ Loss of Use (3.0 x S\$	50.00/day) (S\$)	150.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	1,852.00		
Global Sum S	Settlement (S\$)	1,850.00		

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At: Cn Motors Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 BLK C #01-

41 AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2021)

Parts: 143 HONDA CIVIC 1.6 5AT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJP6539X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*FRONT BUMPER	Deformed	638.20 F	*638.20 FL		
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL		
3	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	25.00 F	*25.00 FL		
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	377.90 F	*- FL		
5	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	45.20 F	*- FL		
6	1		*FRONT R/H HEADLAMP	Cut	1,299.80 F	*790.40 FL		
7	1		*FRONT R/H HEADLAMP LOWER BRACKET	Not Necessary	39.00 F	*- FL		
8	1		*FRONT R/H FENDER	Not Necessary	450.80 F	*- FL		
9	1		*FRONT R/H FENDER COWLING	Not Necessary	85.80 F	*- FL		
10	6		*FRONT R/H FENDER COWLING CLIP	Not Necessary	39.00 F	*- FL		
11	1		*FRONT R/H TYRE	Not Necessary	380.00 F	*- FL		
12	1		*FRONT R/H RIM	Cut	1,200.00 FS	*400.00 FS		
F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	4,645.70	1,883.60		
- List Item Discount on L Items 0.00/20.00% (S\$)				0.00	296.72			
				Total Parts (S\$)	4,645.70	1,586.88		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO CHECK WIRING	New	100.00	30.00				
2	TOWING FEE	New	150.00	0.00				
3	TUFF KOTE	New	150.00	0.00				
4	PANEL BEATING	New	1,000.00	200.00				
5	SPRAY PAINTING	New	1,000.00	400.00				
		Gross Labour Cost (S\$)	2,400.00	630.00				

Report was unsubmitted during this print-out.

< END OF ESTIMATES >