

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012930/ASD3E2

**Date:** 21/12/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00061062000  
**Claimant Vehicle No :** SDK7373Y **Insured Vehicle No :** GBH6532B  
Date of Loss: 22/11/2020 Nature of Claim: TP Claim No: SNM20D204520/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK7373Y**  
Make & Model: MITSUBISHI EVO 10, 2.0 GSR (M) Engine No: 4B11AS7288  
Reg. Date: 07/10/2008 (Man. Year: 2007) Chassis No: CZ4A0000751  
Colour: White Odometer: 151849 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 265/35 R18 Rear Tyre Size: 265/35 R18  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 4,115.40          | 2,004.80          | 2,110.60          | 51.29         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,800.00          | 960.00            | 840.00            | 46.67         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,915.40</b>   | <b>2,964.80</b>   | <b>2,950.60</b>   | <b>49.88</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,300.00</b>   |                   |               |
| <b>(S\$)</b>                             | 5,915.40          | 2,300.00          | 3,615.40          | 61.12         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 414.08            | 161.00            | 253.08            | 61.12         |
| <b>Nett Amount (S\$)</b>                 | <b>6,329.48</b>   | <b>2,461.00</b>   | <b>3,868.48</b>   | <b>61.12</b>  |

### INSPECTION

Date of Assignment: 24/11/2020  
Date Inspected: 24/11/2020 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
Singapore 417921  
Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 21 Dec 2020)  |
| <b>Parts:</b> 143          | MITSUBISHI EVO 10 2.0 GSR (M) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SDK7373Y)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's | Amount     |
|-----|-----|----------|---|---------------|------------|------------|
| 1   | 1   |          | *REAR BOOTLID WEATHER STRIP                 | Not Necessary | 155.00 FL  | *- FL      |
| 2   | 1   |          | *REAR BUMPER                                | Deformed      | 810.00 FL  | *810.00 FL |
| 3   | 1   |          | *REAR BUMPER LOWER LID                      | Cracked       | 348.00 FL  | *348.00 FL |
| 4   | 2   |          | *REAR BUMPER NUMBER PLATE LAMP BRACKET L/R  | Bent          | 36.00 FL   | *36.00 FL  |
| 5   | 2   |          | *REAR BUMPER NUMBER PLATE LAMP L/R          | Cracked       | 78.00 FL   | *78.00 FL  |
| 6   | 2   |          | *REAR BUMPER REFLECTOR L/R                  | Cracked       | 84.00 FL   | *84.00 FL  |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT                  | Not Necessary | 409.00 FL  | *- FL      |
| 8   | 2   |          | *REAR BUMPER SIDE RETAINER L/R              | Necessary     | 58.00 FL   | *58.00 FL  |
| 9   | 1   |          | *REAR BUMPER TOP BRACKET                    | Bent          | 109.00 FL  | *109.00 FL |
| 10  | 1   |          | *REAR END PANEL                             | Repair        | 506.00 FL  | *- FL      |
| 11  | 1   |          | *REAR END PANEL INNER TOP GARNISH           | Deformed      | 149.00 FL  | *149.00 FL |
| 12  | 2   |          | *REAR TAILLAMP L/R                          | Not Necessary | 664.00 FL  | *- FL      |
| 13  | 1   |          | *SET REAR BUMPER CLIPS                      | Necessary     | 50.00 FS   | *30.00 FS  |
| 14  | 1   |          | *REAR BUMPER NUMBER PLATE                   | Cracked       | 120.00 FS  | *80.00 FS  |
| 15  | 1   |          | *REAR BUMPER NUMBER PLATE GARNISH           | Not Necessary | 50.00 FS   | *- FS      |
| 16  | 1   |          | *REAR BUMPER REVERSE CAMERA                 | Damaged       | 800.00 FS  | *380.00 FS |
| 17  | 1   |          | *SET REAR END PANEL INNER TOP GARNISH CLIPS | Necessary     | 30.00 FS   | *10.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>4,456.00</b> | <b>2,172.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 340.60          | 167.20          |
| <b>Total Parts (\$)</b>                                  | <b>4,115.40</b> | <b>2,004.80</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars  | Lab.Type | Repairer's                      | Amount          |
|---------------------|--|----------|---------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                                 |                 |
| 1                   | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR   | New      | 100.00                          | 80.00           |
| 2                   | TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)   | New      | 120.00                          | 40.00           |
| 3                   | TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT  | New      | 800.00                          | 400.00          |
| 4                   | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT | New      | 700.00                          | 400.00          |
| 5                   | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL   | New      | 80.00                           | 40.00           |
|                     |  |          | <b>Gross Labour Cost (\$\$)</b> | <b>1,800.00</b> |
|                     |  |          |                                 | <b>960.00</b>   |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >