

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012932/T1TF3E2  
**Date:** 03/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00067012000
<b>Claimant Vehicle No :</b>	SKT7904K	<b>Insured Vehicle No :</b>	YN9250R
Date of Loss:	20/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204496C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKT7904K</b>	Engine No:	1ZR519261
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053REH104535267
Reg. Date:	23/06/2015 (Man. Year: 2015)	Odometer:	71865 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,604.50	7,440.30	3,164.20	29.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	4,290.00	1,310.00	23.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,204.50</b>	<b>11,730.30</b>	<b>4,474.20</b>	<b>27.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,134.32</b>	<b>821.12</b>	<b>313.20</b>	<b>27.61</b>
<b>Nett Amount (S\$)</b>	<b>17,338.82</b>	<b>12,551.42</b>	<b>4,787.40</b>	<b>27.61</b>

### INSPECTION

Date of Assignment:	24/11/2020		
Date Inspected:	24/11/2020	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	6.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
<b>Parts:</b>	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKT7904K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*HOOD SUB-ASSY	Bent	1,248.80 FS	*1,248.80 FS
4	1		*GRILLE, RADIATOR	Cracked	643.00 FS	*643.00 FS
5	1		*FENDER SUB-ASSY, RH	Bent	908.70 FS	*908.70 FS
6	1		*PLATE, LUGGAGE COMPT	Necessary	35.50 FS	*35.50 FS
7	1		*SUPPORT, FR BUMPER RH	Not Necessary	85.50 FS	*- FS
8	1		*HEADLAMP ASSY, RH	Cracked	2,999.80 FS	*2,999.80 FS
9	1		*HEADLAMP ASSY, LH	Not Necessary	2,999.80 FS	*- FS
10	1		*PANEL SUB-ASSY, COWL LOWER SUB-ASSY COWL	Cut	645.00 FS	*645.00 FS
11	1		*COVER, CYLINDER HEAD	Cracked	410.50 FS	*410.50 FS
12	1		*INSULATOR, HOOD	Deformed	280.10 FS	*280.10 FS
13	1		*HINGE ASSY, HOOD RH	Bent	58.90 FS	*58.90 FS
14	1		*HINGE ASSY, HOOD, LH	Not Necessary	58.90 FS	*- FS
15	1		*REGN PLATE (PO# )	Dented	80.00 FS	*80.00 FS
<b>Total Parts (S\$)</b>					<b>10,604.50</b>	<b>7,440.30</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RESET AND REPROGRAMME ECU	New	180.00	180.00
2	REPLACE AND REFOCUS HEADLAMP	New	180.00	180.00
3	REMOVE ALL NECESSARY DAMAGED PARTS. TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, R/F FENDER AND AFFECTED PORTION OF CAR	New	2,880.00	2,160.00
4	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,360.00	1,770.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,600.00</b>	<b>4,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >