

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012933/UBA3Q2

Date: 08/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SBJ61Y	Insured Vehicle No :	SHC1192L
Date of Loss: 22/11/2020	Nature of Claim: TP	Claim No: MCT20110347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBJ61Y		
Make & Model:	NISSAN SUNNY, 1.6 EX (A)	Engine No:	QG16410288
Reg. Date:	18/07/2006 (Man. Year: 2006)	Chassis No:	JN1CFAN16Z0102173
Colour:	Gold	Odometer:	87047 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,904.29	2,453.92	3,450.37	58.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,030.00	860.00	45.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,794.29	3,483.92	4,310.37	55.30
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	7,794.29	2,200.00	5,594.29	71.77
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		2,486.45		

INSPECTION

Date of Assignment:	24/11/2020	
Date Inspected:	24/11/2020 Inspected At:	T K Lee Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2021)
Parts:	143	NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBJ61Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Buckled	1,085.50 FN	*1,085.50 FN
2	2		*FRONT BONNET HINGE LH/RH	Serviceable	72.80 FN	*- FN
3	1		*FRONT BONNET RUBBER	Not Necessary	33.90 FN	*- FN
4	1		*FRONT BONNET LOCK	Serviceable	50.60 FN	*- FN
5	2		*FRONT HEADLAMP LH/RH	Serviceable	1,172.80 FN	*- FN
6	2		*FRONT HEADLAMP HOLDER CLIPS	Not Necessary	10.20 FN	*- FN
7	1		*FRONT GRILLE	Cracked	258.60 FN	*258.60 FN
8	1		*FRONT GRILLE EMBLEM LOGO	Necessary	60.60 FN	*60.60 FN
9	1		*FRONT BUMPER	Distorted	474.10 FN	*474.10 FN
10	1		*FRONT BUMPER MOULDING	Distorted	215.60 FN	*215.60 FN
11	1		*FRONT BUMPER TOP BEAM	Bent	200.30 FN	*200.30 FN
12	1		*FRONT BUMPER REINFORCEMENT	Bent	354.10 FN	*354.10 FN
13	2		*FRONT BUMPER BRACKET LH/RH	Not Necessary	245.00 FN	*- FN
14	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	56.60 FN	*- FN
15	1		*FRONT SUPPORT PANEL	Repair	669.80 FN	*- FN
16	1		*AIR CON CONDENSER	Serviceable	548.30 FN	*- FN
17	1		*RADIATOR	Not Necessary	787.10 FN	*- FN
18	2		*RADIATOR TOP BRACKET	Not Necessary	42.20 FN	*- FN
19	1		*SET FRONT NUMBER PLATE WITH CASING	Bent	50.00 FS	*40.00 FS
20	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
21	1		*AIR CON OIL	Not Necessary	45.00 FS	*- FS
22	1		*SET RADIATOR COOLANT	Not Necessary	25.00 FS	*- FS
23	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,538.10	2,718.80
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	633.81	264.88
Total Parts (\$\$)	5,904.29	2,453.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK OUT DENT ,CUT /WELD FRONT SUPPORT PANEL AND REPLACE ACCIDENT PARTS	New	800.00	400.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	900.00	580.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO REMOVE ,REPLACE CONDENSER AND REFILL GAS	New	100.00	0.00
5	TO TUFF-KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			1,890.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >