

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20012934/EBA3Q2

Date:

18/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900097083

Claimant Vehicle No : SHA1251K**Insured Vehicle No :**

SML2832K

Date of Loss: 22/11/2020

Nature of Claim:

TP

Claim No:

3712025275SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA1251K**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No:

2ZRS055703

Reg. Date: 05/07/2017 (Man. Year: 2017)

Chassis No:

JTDKB3FU803561141

Colour: Blue

Odometer:

358019 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Bridgestone 4 mm

Rear Left Side:

Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side:

Bridgestone 4 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,373.02	998.22	374.80	27.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	550.00	230.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,153.02	1,548.22	604.80	28.09
Approved Total (Overridden) (S\$)		1,250.00		

(S\$)	2,153.02	1,250.00	903.02	41.94
+ GST 7.00/7.00% (S\$)	150.71	87.50	63.21	41.94
Nett Amount (S\$)	2,303.73	1,337.50	966.23	41.94
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,865.70		
Global Sum Settlement (S\$)		1,850.00		

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 24/11/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Broken	458.60 FL	*458.60 FL
2	1		*GUARD -REAR BUMPER C	Cut	552.60 FL	*552.60 FL
3	1		*REINFORCEMENT SUB-A	Not Necessary	318.80 FL	*- FL
4	1		*COVER REAR BUMPER -T	Cut	82.70 FL	*82.70 FL
5	1		*REVERSE SENSOR ASSY	Not Necessary	135.70 FS	*- FS
6	1		*BUMPER PROTECTOR MA	Necessary	50.00 FS	*50.00 FS
7	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
8	1		*FILLER -REAR BUMPER	Broken	148.40 FL	*148.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,768.80	1,314.30
- List Item Discount on L Items 25.00/25.00% (\$)	395.78	316.08
Total Parts (\$)	1,373.02	998.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >