

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012935/EPA3Q2

**Date:** 03/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900109220

**Claimant**  
**Vehicle No :** SHD1439X **Insured Vehicle No :** YP6605K

Date of Loss: 23/11/2020 Nature of Claim: TP Claim No: 9450401836SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD1439X</b>		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ135678
Reg. Date:	16/08/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ131317
Colour:	Silver	Odometer:	273131 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,895.10	3,212.10	3,683.00	53.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,010.00	1,060.00	51.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,965.10</b>	<b>4,222.10</b>	<b>4,743.00</b>	<b>52.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>(S\$)</b>	8,965.10	3,350.00	5,615.10	62.63
<b>+ GST 7.00/7.00% (S\$)</b>	627.56	234.50	393.06	62.63
<b>Nett Amount (S\$)</b>	<b>9,592.66</b>	<b>3,584.50</b>	<b>6,008.16</b>	<b>62.63</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$67.41/day) (S\$)</b>		202.23		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,938.73</b>		

### INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 24/11/2020 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 3.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR N/S & O/S TAIL LAMP	Not Necessary	642.60 FL	*- FL
2	2		*REAR N/S & O/S REFLECTOR	Not Necessary	590.20 FL	*- FL
3	1		*END PANEL	Not Necessary	853.85 FL	*- FL
4	1		*TAILGATE	Dented	2,292.30 FL	*2,292.30 FL
5	1		*TAILGATE LOWER GARNISH	Broken	362.61 FL	*362.61 FL
6	1		*TAILGATE LOCK	Not Necessary	216.48 FL	*- FL
7	1		*TAILGATE STRIKER	Not Necessary	36.50 FL	*- FL
8	2		*TAILGATE HINGE	Not Necessary	57.00 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	276.98 FL	*- FL
10	2		*REAR LICENSE PLATE LAMP	Not Necessary	37.20 FL	*- FL
11	1		*REAR WIPER MOTOR	Not Necessary	261.40 FL	*- FL
12	1		*REAR WIPER ARM	Not Necessary	30.60 FL	*- FL
13	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
14	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
15	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
16	1		*REAR BUMPER	Broken	811.11 FL	*811.11 FL
17	1		*REAR BUMPER SPONGE	Not Necessary	79.20 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Not Necessary	815.64 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT CENTRE	Not Necessary	79.20 FL	*- FL
20	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	104.40 FL	*- FL
21	2		*REAR BUMPER N/S & O/S REFLECTOR	Not Necessary	215.00 FL	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
23	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*80.00 FS
25	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*20.00 FS
26	1		*REAR NO PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
27	1		*SEALANT	Necessary	50.00 FS	*20.00 FS
28	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,464.87</b>	<b>3,922.62</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,569.77</b>	<b>710.52</b>
<b>Total Parts (\$\$)</b>	<b>6,895.10</b>	<b>3,212.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	30.00
2	TO REPLACE/REFIT THE NEW REAR WINDSCREEN GLASS INTO NEW SHELL TAILGATE	New	120.00	120.00
3	TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE TAILGATE INTO NEW TAILGATE,TEST WIPER MOTOR AND WATER ETC	New	120.00	30.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/CUT AND WELD ON THE END PANEL.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE SAME ETC	New	800.00	400.00
5	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,TAILGATE,TAILGATE LOWER GARNISH,END PANEL	New	800.00	400.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,070.00</b>	<b>1,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >