

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20012943/QEA3Q2  
**Date:** 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100483786
<b>Claimant Vehicle No :</b>	YP8278H	<b>Insured Vehicle No :</b>	SLG3377P
Date of Loss:	13/11/2020	Nature of Claim:	TP
		Claim No:	5991490726SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YP8278H</b>	Engine No:	GH7212346
Make & Model:	UD TRUCKS PKC8ELN5EP, 7.0 D (M)	Chassis No:	JNCL0F1A3JU026832
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	57769 km
Colour:	White		
Engine Capacity:	7013 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	11 R22.5	Rear Tyre Size:	11 R22.5
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,896.70	0.00	6,896.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,000.00	630.00	38.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,526.70</b>	<b>1,000.00</b>	<b>7,526.70</b>	<b>88.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>596.87</b>	<b>70.00</b>	<b>526.87</b>	<b>88.27</b>

<b>Nett Amount (S\$)</b>	<b>9,123.57</b>	<b>1,070.00</b>	<b>8,053.57</b>	<b>88.27</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 01/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Think One Autocare Pte Ltd (HQ)  
 No. 60 Jalan Lam Huat #02-32, Carros Centre  
 Singapore 737869

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER ASSY	Repair	3,620.00 FL	*- FL	
2	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,855.00 FL	*- FL	
3	2		*HEADLAMP ASSY LH	Serviceable	2,188.00 FL	*- FL	
					<b>Sub Total (\$)</b>	<b>7,663.00</b>	<b>0.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	766.30	0.00
					<b>Total Parts (\$)</b>	<b>6,896.70</b>	<b>0.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS ATTACHMENTS	New	800.00	500.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	800.00	500.00
3	TO CONDUCT HEADLAMP ALIGNMENT	New	30.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,630.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >