

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20012954/DQF3Q2

**Date:** 09/12/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29088694QMY

**Claimant**  
**Vehicle No :** SKH5602H

**Insured Vehicle No :** SJZ3443E

Date of Loss: 24/11/2020

Nature of Claim: TP

Claim No: 631277

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH5602H**

Make & Model: HONDA CIVIC, 1.6 VTI-S (A)

Engine No: R16B11002064

Reg. Date: 20/12/2012 (Man. Year: 2012)

Chassis No: JHMFB1630CS201562

Colour: White

Odometer: 121371 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,351.64	2,660.88	6,690.76	71.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,940.00	2,310.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,601.64</b>	<b>4,600.88</b>	<b>9,000.76</b>	<b>66.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>(S\$)</b>	13,601.64	3,700.00	9,901.64	72.80
<b>+ GST 7.00/7.00% (S\$)</b>	952.11	259.00	693.11	72.80
<b>Nett Amount (S\$)</b>	<b>14,553.75</b>	<b>3,959.00</b>	<b>10,594.75</b>	<b>72.80</b>

### INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-

08 AMK AutoPoint

Singapore 568047

Estimated Period of Repair: 4.0 days

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2020)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI-S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH5602H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	984.25 FL	*876.50 FL
2	2		*BOOTLID LAMP LH/RH	Not Necessary	791.60 FL	*- FL
3	1		*BOOTLID LOGO	Necessary	79.40 FL	*79.40 FL
4	1		*BOOTLID CIVIC EMBLEM	Necessary	92.50 FL	*92.50 FL
5	1		*BOOTLID 1.6 EMBLEM	Necessary	66.20 FL	*66.20 FL
6	1		*BOOTLID I-VTEC EMBLEM	Necessary	98.60 FL	*98.60 FL
7	1		*BOOTLID LOCK	Serviceable	389.70 FL	*- FL
8	1		*BOOTLID SWITCH	Not fitted	189.40 FL	*- FL
9	2		*BOOTLID HINGE LH/RH	Not Necessary	196.00 FL	*- FL
10	1		*BOOTLID INNER TRIM	Not Necessary	399.20 FL	*- FL
11	1		*BOOT LID WEATHER STRIP	Necessary	285.70 FL	*178.60 FL
12	1		*TAIL LAMP LH/RH	O/s Cut/N/s Not Necessary	1,391.80 FL	*385.20 FL
13	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	203.80 FL	*- FL
14	1		*REAR BUMPER	Distorted/Cracked	1,012.80 FL	*669.40 FL
15	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	98.00 FL	*- FL
16	1		*REAR BUMPER SPONGE	Not fitted	219.00 FL	*- FL
17	1		*REAR BUMPER SENSOR (4 Pcs)	O/s Damaged/N/s Not Necessary	1,240.00 FL	*400.00 FL
18	4		*REAR BUMPER SENSOR HOLDER	Serviceable	80.00 FL	*- FL
19	1		*REAR BUMPER SENSOR WIREHARNES	Not Necessary	840.00 FL	*- FL
20	1		*REAR END PANEL	Dented	895.30 FL	*314.50 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	295.80 FL	*77.70 FL
22	1		*SPARE WHEEL PANEL	Not Necessary	1,328.00 FL	*- FL
23	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
26	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*REAR NO PLATE & CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,587.05</b>	<b>3,308.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,235.41</b>	<b>647.72</b>
<b>Total Parts (\$\$)</b>	<b>9,351.64</b>	<b>2,660.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	750.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	750.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>4,250.00</b>	<b>1,940.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**