

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20012957/GQF3E2

**Date:** 16/04/2021

### REFERENCE

Insured/Claimant: CHUA CHENG HOE Policy No: DMPCSNW00068862000

Date of Loss: 12/11/2020 Nature of Claim: OD Claim No: SNM20D204359/C01/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG222G**  
Make & Model: LEXUS RX200T, 2.0 F SPORT S/R (A) Engine No: 8ARW170583  
Reg. Date: 18/01/2016 (Man. Year: 2015) Chassis No: JTJBAMCA502000952  
Colour: White Odometer: 76003 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$126,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 265/35 ZR22 Rear Tyre Size: 265/35 ZR22  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	42,745.60	23,738.75	19,006.85	44.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,529.41	4,675.49	-146.08	-3.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>47,275.01</b>	<b>28,414.24</b>	<b>18,860.77</b>	<b>39.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,309.25</b>	<b>1,989.00</b>	<b>1,320.25</b>	<b>39.90</b>
<b>Nett Amount (S\$)</b>	<b>50,584.26</b>	<b>30,403.24</b>	<b>20,181.02</b>	<b>39.90</b>

### INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 25/11/2020 Inspected At:

No 2 Kaki Bukit Ave 2 B# 01-33 Autohub  
Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 14.0 days

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2021)
<b>Parts:</b> M1-SUV	LEXUS RX200T 2.0 F SPORT S/R (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGG222G)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		<b>*TOTAL PARTS</b>		39,805.60 F	*20,798.75 F	
<b><u>Supplementary #1</u></b>							
2	1		<b>*SUBFRAME</b>	Bent	1,700.00 F	*1,700.00 F	
3	1		<b>*LOWER ARM</b>	Bent	180.00 F	*180.00 F	
4	1		<b>*RACK END</b>	Bent	90.00 F	*90.00 F	
<b><u>Supplementary #2</u></b>							
5	1		<b>*R/F WINDOW FRT GUIDE</b>	Bent	170.00 F	*170.00 F	
6	1		<b>*R/R DOOR FRAME MLDG</b>	Necessary	250.00 F	*250.00 F	
7	1		<b>*R/R WHEEL ARCH MLDG</b>	Cut	230.00 F	*230.00 F	
8	1		<b>*L/F AXLE CARRIER BRG</b>	Necessary	80.00 F	*80.00 F	
9	1		<b>*R/F AXLE CARRIER BRG</b>	Necessary	80.00 F	*80.00 F	
10	1		<b>*L/R AXLE CARRIER BRG</b>	Necessary	80.00 F	*80.00 F	
11	1		<b>*R/R AXLE CARRIER BRG</b>	Necessary	80.00 F	*80.00 F	
					<b>Total Parts (S\$)</b>	<b>42,745.60</b>	<b>23,738.75</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOTAL LABOUR	New	3,040.80	2,940.00
2	TOTAL PAINTING	New	1,488.61	1,735.49
			<b>Gross Labour Cost (S\$)</b>	<b>4,529.41</b>
				<b>4,675.49</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >