

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 26 Nov 2020

Preliminary Advice

Vehicle No	: SGG222G	Accident Date	: 12/11/2020
Make	: LEXUS RX200T	Policy No.	: DMPCSNW00068862000
Assignment Date	: 24/11/2020	Excess	: S\$0.00
Date of Inspection	: 25/11/2020	Est. Duration of Repair	: 14
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,335.01
Revised Amount	:S\$	29,729.96
Check Items (Estimated)	:S\$	11,184.50
Total	:S\$	40,914.46

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	126,000.00
COE / PARF Rebate	:S\$	88,159.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,841.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE WITHIN \$37,000.00.