

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20012962/T1GS3Q2
Date: 05/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800156473	
Claimant Vehicle No : SMR2323G	Insured Vehicle No : SDX344J	
Date of Loss: 20/11/2020	Nature of Claim: TP	Claim No: 3334800791SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR2323G		
Make & Model: BMW X5 XL, 3.0 (A)	Engine No: 00369999N55B30A	
Reg. Date: 23/10/2017 (Man. Year: 2017)	Chassis No: WBAKR020000S46426	
Colour: Silver	Odometer: 59778 km	
Engine Capacity: 2979 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19	Rear Tyre Size: 255/50 R19	
Front Left Side: Michelin 6 mm	Rear Left Side: Michelin 6 mm	
Front Right Side: Michelin 6 mm	Rear Right Side: Michelin 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	275.65	235.65	40.00	14.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,942.65	2,319.65	623.00	21.17
+ GST 7.00/7.00% (\$\$)	205.99	162.38	43.61	21.17
Nett Amount (\$\$)	3,148.64	2,482.03	666.61	21.17
+ Loss of Use (3.0 x S\$110.00/day) (\$\$)		330.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,814.03		

INSPECTION

Date of Assignment: 02/12/2020		
Date Inspected: 02/12/2020 Inspected At:		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair: 3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*REAR BUMPER TRIM STRIP (PURE)	Cut	181.65 FS	*181.65 FS
3	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
				Total Parts (\$\$)	275.65	235.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR BUMPER INCLUDING REPLACING BUMPER STRIPE	New	1,275.00	850.00
2	TO PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING RECONNECT TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,667.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >