

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012965/EES3Q2
Date: 18/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700093087
Claimant Vehicle No :	SH9647H	Insured Vehicle No :	SLV4995U
Date of Loss:	21/11/2020	Nature of Claim:	TP
		Claim No:	9849037449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9647H	Engine No:	G4LEJU111927
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU115143
Reg. Date:	08/11/2018 (Man. Year: 2018)	Odometer:	287418 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,498.92	1,515.08	3,983.84	72.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,300.00	630.00	32.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,428.92	2,815.08	4,613.84	62.11
+ GST 7.00/7.00% (S\$)	520.02	197.06	322.96	62.11

Nett Amount (\$)	7,948.94	3,012.14	4,936.80	62.11
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	24/11/2020		
Date Inspected:	24/11/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster:	CHEN TSUE YEE	Manager:	CHUA ZHEN LI
------------------	---------------	-----------------	--------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cut	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER GRILLE RH	Not Necessary	93.45 FL	*- FL
3	1		*FRONT DAYLIGHT RH	Not Necessary	642.50 FL	*- FL
4	1		*FRONT BUMPER BRACKET RH	Not Necessary	35.00 FL	*- FL
5	1		*HEADLAMP ASSY RH	Not Necessary	1,993.65 FL	*- FL
6	1		*HEAD SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
7	1		*FRONT RH FENDER	Dented	588.80 FL	*588.80 FL
8	1		*FRONT FENDER SHIELDRLH	Not Necessary	164.70 FL	*- FL
9	1		*FENDER EMBLEM BLUE -DRIVE	Necessary	26.60 FL	*26.60 FL
10	1		*FRONT RH WHEEL COVER	Cut	346.40 FL	*346.40 FL
11	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
12	1		*REAR BUMPER CENTRE MOULDING	Crushed	451.25 FL	*451.25 FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
14	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
15	1		*REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
16	1		*REAR NUMBER PLATE W/HOLDER	Broken	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,816.15	1,881.35
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,317.23	366.27
Total Parts (\$\$)	5,498.92	1,515.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING FRONT /REAR	New	800.00	640.00
2	SPRAY PAINTING FRONT /REAR	New	800.00	600.00
3	CHECK LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	0.00
5	TUFF COATING	New	90.00	30.00
6	REMOVE/REFIX A/C CONDENDER & CHARGE GAS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,930.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >