

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
6 Defu Avenue 1
Singapore 539537

Marymount
600 Sin Ming Avenue
Singapore 575733

Our Ref : 305435290

Date : 24.11.2020

Time of Fax : _____

AIG

Via Fax : EMAIL

Your Insured : SLV 4995U

Date of Acc : 21.11.2020

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SH9647H

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811

Jumari Masudin Tel no. 62148315 or Hp no. 96355305

Chiang Liat Choon Tel no. 62148314

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully


for Vice President

Crash Repairs & Claims Recovery

REPAIR ESTIMATE*

VEHICLE NO SH9647H

DATE 24/11/20

MAKE :

MODEL : HYUNDAI IONIQ G2

/CHIANG /AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$418.30
1	FRONT BUMPER GRILLE RH			\$93.45
1	FRONT DAYLIGHT RH			\$642.50
1	FRONT BUMPER BRACKET RH			\$35.00
1	HEADLAMP ASSY RH			\$1,993.65
1	HEAD SUPPORT PANEL			\$949.30
1	FRONT RH FENDER			\$588.80
1	FRONT FENDER SHIELDRLH			\$164.70
1	FENDER EMBLEM BLUE -DRIVE			\$26.60
1	FRONT RH WHEEL COVER			\$346.40
1	REAR BUMPER COVER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
10	REAR BUMPER CLIPS			\$22.00
	SUB TOTAL			\$6,586.15
	20.00%			\$1,317.23
	DISCOUNTED TOTAL			\$5,268.92
1	REVERSE SENSOR			\$180.00
1	REAR NUMBER PLATE W/HOLDER			\$50.00
				\$230.00
	Labour Charge			
	Panel Beating FRONT/REAR			\$800.00
	Spray painting FRONT/REAR			\$800.00
	Check Lighting			\$60.00
	Remove/refix reverse sensor			\$60.00
	Tuff coating			\$90.00
	Remove/refix A/c condenser & charge gas			\$120.00
	TOTAL LABOUR			\$1,930.00
	ESTIMATE TOTAL			\$7,428.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				