Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20012969/QQF3Q2

Date: 29/12/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2070012906 Policy No: Claimant FBK8826A Insured Vehicle No: SMR9973J Vehicle No:

Date of Loss: 29/10/2020 Nature of Claim: ΤP Claim No: 8898769638SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**FBK8826A** Reg No:

YAMAHA FZN150, 149cc Make & Model: Engine No: G3E3E0028395

Reg. Date: 15/03/2016 (Man. Year: 2016) Chassis No: ME1RG1612G2001787

Colour: Odometer: 53570 km Black

**Engine Capacity:** 149 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 100/80-17 Rear Tyre Size: 100/80-17 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,135.60	1,669.30	466.30	21.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	390.00	230.00	37.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,755.60	2,059.30	696.30	25.27
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,755.60	1,650.00	1,105.60	40.12
+ GST 7.00/7.00% (S\$)	192.89	115.50	77.39	40.12
Nett Amount (S\$)	2,948.49	1,765.50	1,182.99	40.12

**INSPECTION** 

Date of Assignment: 24/11/2020

Date Inspected: 25/11/2020 Inspected At: Sin Boon Motor Co (HQ)

10 Admiralty Street, #01-10/11,

Northlink Building Singapore 757695

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: SHIAU CHAN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR	Crumpled	60.00 FL	*60.00 FL
2	1		*HANDLE BAR	Bent	80.00 FL	*80.00 FL
3	1		*BRAKE LEVER	Crumpled	30.00 FL	*30.00 FL
4	1		*CLUTHC LEVER	Crumpled	30.00 FL	*30.00 FL
5	1		*HANDLE BAR END PLASTIC COVER	Crumpled	20.00 FL	*20.00 FL
6	1		*FRONT RIGHT SIGNAL	Scratched	40.00 FL	*40.00 FL
7	1		*FRONT LEFT SIGNAL	Serviceable	40.00 FL	*- FL
8	1		*FRONT LIGHT COVER BLACK	Scratched	55.00 FL	*55.00 FL
9	1		*LEFT SIDE TANK COVER	Scratched	165.00 FL	*140.00 FL
10	1		*RIGHT SIDE TANK COVER	Scratched	165.00 FL	*140.00 FL
11	1		*SET HAND GRIP	Broken	30.00 FL	*30.00 FL
12	1		*EXHAUST COVER BLACK (BIG)	Scratched	55.00 FL	*55.00 FL
13	1		*EXHAUST COVER SILVER END CAP (SMALL)	Scratched	49.00 FL	*49.00 FL
14	1		*LEFT SIDE CENTER FAIRING	Missing	80.00 FL	*80.00 FL
15	1		*RADIATOR COVER	Missing	55.00 FL	*55.00 FL
16	1		*SET MAIN STAND & BOLT	Bent	202.00 FL	*185.00 FL
17	1		*FRONT BRAKE DISC	Serviceable	140.00 FL	*- FL
18	1		*FRONT BRAKE RESERVOIR	Serviceable	160.00 FL	*- FL
19	1		*RIGHT SIDE REAR SIDE COVER	Scratched	78.00 FL	*78.00 FL
20	1		*SIDE STAND	Bent	30.00 FL	*30.00 FL
21	1		*IU	Scratched	158.00 FS	*158.00 FS
22	1		*FRONT NUMBER PLATE	Scratched	20.00 FS	*20.00 FS
23	1		*CARGO BOX COOCASE	Scratched	550.00 FS	*450.00 FS
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.	0 1 T ( ) (0A)	0.000.00	4 705 00
	Sub Total (S\$)				2,292.00	1,785.00
	- List Item Discount on L Items 10.00/10.00% (S\$) 156.40 115.70					
			1	Γotal Parts (S\$)	2,135.60	1,669.30
	Report was unsubmitted during this print-out.					

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 29/12/2020

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	FORK ALIGNMENT	New	230.00	150.00			
2	TOW	New	60.00	60.00			
3	LABOUR	New	330.00	180.00			
		Gross Labour Cost (S\$)	620.00	390.00			
	R	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >