

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20012970/QBS3Q2

**Date:** 27/04/2021

#### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0004162_01
<b>Claimant Vehicle No :</b>	SG5870K	<b>Insured Vehicle No :</b>	GBG6017C
Date of Loss:	17/11/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002519

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SG5870K</b>		
Make & Model:	MAN A95, 10.5 D (A)	Engine No:	50344832274486
Reg. Date:	16/11/2017 (Man. Year: 2016)	Chassis No:	WMAA95ZZ8G7003550
Colour:	Multi-colour	Odometer:	0 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,149.40	5,906.61	1,242.79	17.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,742.00	3,307.00	435.00	11.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,891.40</b>	<b>9,213.61</b>	<b>1,677.79</b>	<b>15.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,891.40</b>	<b>8,050.00</b>	<b>2,841.40</b>	<b>26.09</b>
<b>+ Loss of Use (6.0 x S\$250.00/day) (S\$)</b>		1,500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>9,557.00</b>		

#### INSPECTION

Date of Assignment:	24/11/2020	
Date Inspected:	24/11/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** OI SUN PIN

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Mar 2021)	
<b>Parts:</b>	N/A	MAN A95 10.5 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SG5870K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE LAMP BULB (A95 MAN)	Crumpled	235.00 F	*235.00 FL
2	1		*REAR LAMP BULB (A95 MAN)	Scratched	245.00 F	*245.00 FL
3	1		*SIDE PANEL R7	Dented	1,115.00 F	*1,115.00 FL
4	1		*SIDE PANEL R9	Crumpled	500.00 F	*500.00 FL
5	1		*SIDE GLASS R10	Broken	641.00 F	*641.00 FL
6	1		*LAMP ,STOP LED (MAN BUS)	Crumpled	1,141.70 F	*1,141.70 FL
7	1		*LAMP ,INDICATOR LED (MAN BUS)	Cracked	1,274.10 F	*1,274.10 FL
8	1		*A95 WHEEL COVER PLATE WITH ADHESIVE LABEL	Bent	513.60 F	*513.60 FL
9	1		*WHEEL ARCH TRIM FRP	Scratched	187.50 F	*187.50 FL
10	1		*SMRT STICKERS	Necessary	35.00 FS	*35.00 FS
11	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
12	12		*ADHESIVE DIRECT GLAZING	Necessary	444.00 FS	*444.00 FS
13	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS
14	1		*SIDE PANEL R8	Repair	657.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,149.40</b>	<b>6,491.90</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	585.29
<b>Total Parts (\$)</b>	<b>7,149.40</b>	<b>5,906.61</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	2,120.00	1,855.00
2	TO PUTTY & RESPRAY	New	1,622.00	1,452.00
<b>Gross Labour Cost (S\$)</b>			<b>3,742.00</b>	<b>3,307.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >