



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18017059/Kha3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 15-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 3481J	Veh. Inspected	SHB 9602Z
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D04499/C01/1	Excess (\$)	0.00
Assign From		Assign Date	18/09/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB122741	Colour	WHITE /RED
Odometer	505518	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	9 mm
L/H Front Tyre	195/65 R15	GITI	9 mm
R/H Rear Tyre	195/65 R15	GITI	9 mm
L/H Rear Tyre	195/65 R15	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/09/2018	Inspection Date	18/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9602Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	DISTORTED	102.00	102.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	-
1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	-
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	-
1	HEADLAMP LH	CRACKED	816.00	816.00
1	HEADLAMP RH	TO REPAIR SEE LABOUR	611.16	-
1	FRONT FENDER LH	BUCKLED	837.60	837.60
1	FRONT FENDER LINER LH	SERVICEABLE	47.00	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	-
1	FRONT HUB UNIT	SERVICEABLE	376.00	-
1	FRONT DISC BRAKE LH	SERVICEABLE	157.55	-
1	FRONT STRUT BAR BRACKET LH	TO REPAIR SEE LABOUR	235.01	-
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	-
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET LH	TO REPAIR SEE LABOUR	105.75	-

Report Ref No. CC3/CTI18017059/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	-
1	FRONT BEAM A- IMPACT LH	SERVICEABLE	214.00	-
	LESS 10%DISCOUNT		-820.55	-295.76
			7,384.97	2,661.84
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER LINER CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	-
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	330.00	-
			770.00	-
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT BUMPER LOWER STIFFENER,FRONT BUMPER BRACKET LH,FRONT BUMPER BRACKET RH,HEADLAMP LH INNER PANEL,FRONT FENDER INNER WHEEL HOUSE PANEL LH,FRONT STRUT BAR BRACKET LH AND FRONT STABILIZER BAR BRACKET LH.		3,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,200.00	400.00
	TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	440.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT AND SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			8,450.00	820.00
GRAND TOTAL			16,604.97	3,481.84

Report Ref No. CC3/CTI18017059/Kha3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	----------

Report Ref No. CC3/CTI18017059/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 9602Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

