3/30/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20012971/R1BS3Q2

Date:

30/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900118080-01

Claimant Vehicle

FBK6017G

Insured Vehicle No: SJH5343S

17/11/2020 Date of Loss:

Nature of Claim: TP Claim No: 7771390173SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Reg. Date:

No:

FBK6017G

Make & Model:

YAMAHA SUPER TENERE, 1.2

17/11/2015 (Man. Year: 2015)

Engine No: Chassis No: Odometer:

P404E003928 JYADP041000001547

50423 km

Colour: Multi-colour

Engine Capacity: Market Value/New Car Price:

1199 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): **Engine Modification:**

Yes

Footbrake (Serviceable): Yes

No Pre-accident Condition:

CONDITION OF TYRES

Handbrake (Serviceable):

Front Tyre Size: Front Left Side:

110/80 R19 Bridgestone 4 mm

Yes

Rear Tyre Size: Rear Left Side:

150/70 R17 Bridgestone 4 mm

Rear Right Side: 0 mm

Front Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,262.50	2,565.00	697.50	21.38
Miscellaneous Items		0.00	0.00	0.00	
Labour		160.00	100.00	60.00	37.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,422.50	2,665.00	757.50	22.13
	Approved Total (Overridden) (S\$)		2,100.00		
	(S\$)	3,422.50	2,100.00	1,322.50	38.64
	+ GST 7.00/7.00% (S\$)	239.58	147.00	92.58	38.64
	Nett Amount (S\$)	3,662.08	2,247.00	1,415.08	38.64
	+ Loss of Use (2.0 x S	\$35.00/day) (S\$)	70.00		
	N	ett Liability (S\$)	2,317.00		
	Global Sum	Settlement (S\$)	2,250.00		

INSPECTION

Date Inspected:

Date of Assignment:

24/11/2020

25/11/2020

Inspected At:

Southern Motor (HQ)

BLK 1006 BUKIT MERAH LANE 2, #01-10

Singapore 159762

Estimated Period of Repair:

2.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=972147&extid=349587&CFID=83198147&C... 1/4

MOHD RASUL CHUA ZHEN LI Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Serviceable	235.00 FL	*- FL
2	1		*HANDLE GUARD	Scratched	285.00 FL	*285.00 FL
3	1		*CENTRE FAIRING	Scratched	325.00 FL	*325.00 FL
4	1		*ENGINE GUARD	Scratched	380.00 FL	*380.00 FL
5	1		*YAMAHA REAR SIDE BOX COMP	Bent	2,400.00 FL	*1,860.00 FL
F=Fra	nchise	part. L=ListItem	nDisc.			
				Sub Total (S\$)	3,625.00	2,850.00
			- List Item Discount on	L Items 10.00/10.00% (S\$)	362.50	285.00
				Total Parts (S\$)	3,262.50	2,565.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 LABOUR	New	160.00	100.00
	Gross Labour Cost (S\$)	160.00	100.00
Repor	t was unsubmitted during this print-out.		

< END OF ESTIMATES >