

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012975/KGA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100439444
Claimant Vehicle No :	SJB2582U	Insured Vehicle No :	SGP6876H
Date of Loss:	18/11/2020	Nature of Claim:	TP
		Claim No:	3921413240SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB2582U	Engine No:	HRA2463241A
Make & Model:	NISSAN PULSAR, 1.2 DIG-T CVT (A)	Chassis No:	VSKDDAC13U0109741
Reg. Date:	18/09/2017 (Man. Year: 2017)	Odometer:	44392 km
Colour:	Red		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R17	Rear Tyre Size:	205/50 R17
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	866.70	866.70	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	660.00	220.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,746.70	1,526.70	220.00	12.60
+ GST 7.00/7.00% (S\$)	122.27	106.87	15.40	12.60
Nett Amount (S\$)	1,868.97	1,633.57	235.40	12.60
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		1,783.57		
Global Sum Settlement (S\$)		1,750.00		

INSPECTION

Date of Assignment:	24/11/2020	
Date Inspected:	02/02/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	870.00 FN	*870.00 FN
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	75.00 FN	*75.00 FN
3	6		*REAR BUMPER CLIPS	Necessary	18.00 FN	*18.00 FN
F=Franchise part. N=NettItemDisc.						
Sub Total (S\$)					963.00	963.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)					96.30	96.30
Total Parts (S\$)					866.70	866.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,REAR BUMPER LOWER SKIRT ,REVERSE SENSOR ,REALIGN & RESET REVERSE SENSOR ,KNOCK & REPAIR REAR RH FENDER	New	380.00	260.00
2	PUTTY & RESPRAY ON REAR BUMPER ,REAR RH FENDER	New	500.00	400.00
Gross Labour Cost (\$\$)			880.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >