

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012980/ESF3E2

Date: 21/12/2020

REFERENCE

Insured/Claimant: K & S ELECTRICAL ENGINEERING

Policy No: 1900000801

Date of Loss: 23/11/2020

Nature of Claim: OD

Claim No: 7938030526SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG9793U**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGJH709837

Reg. Date: 08/01/2019 (Man. Year: 2018)

Chassis No: KNAF3416MK5020494

Colour: Grey

Odometer: 53866 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$65,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,521.00	4,928.40	5,592.60	53.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	2,270.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,791.00	7,198.40	5,592.60	43.72
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,491.00	6,898.40	5,592.60	44.77
+ GST 7.00/7.00% (S\$)	874.37	482.89	391.48	44.77
Nett Amount (S\$)	13,365.37	7,381.29	5,984.08	44.77

INSPECTION

Date of Assignment: 25/11/2020

Date Inspected: 26/11/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
4	1		*GRILLE-FRONT BUMPER (4PCS)	Broken (1Pc Only)	1,940.00 F	*485.00 FL
5	1		*GRILLE ASSY-RADIATOR	Broken	328.00 F	*328.00 FL
6	1		*GARNISH-RADIATOR GRILLE	Crushed	38.00 F	*38.00 FL
7	1		*MOULDING-FRONT BUMPER, LH	Not Necessary	216.00 F	*- FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
9	1		*PANEL ASSY-HOOD	Dented	1,502.00 F	*1,502.00 FL
10	1		*HINGE ASSY-HOOD, LH	Bent	43.00 F	*43.00 FL
11	1		*HINGE ASSY-HOOD, RH	Bent	43.00 F	*43.00 FL
12	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 F	*- FL
13	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 F	*675.00 FL
14	1		*LAMP ASSY-HEAD, RH	Not Necessary	2,210.00 F	*- FL
15	1		*LAMP ASSY-HEAD, LH	Broken	2,210.00 F	*2,210.00 FL
16	1		*ORNAMENT-KIA NO.115	Necessary	32.00 F	*32.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,521.00	6,143.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,214.60
Total Parts (\$\$)	10,521.00	4,928.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW BONNET, FRT BUMPER	New	800.00	800.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET	New	700.00	700.00
3	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
4	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TOP UP AIRCON GAS	New	80.00	80.00
8	REPLACE FRONT SUPPORT PANEL	New	400.00	400.00
Gross Labour Cost (\$\$)			2,270.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >