

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012981/AGS3Q2

Date: 30/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001035_01
Claimant Vehicle No :	SMM9244G	Insured Vehicle No :	GW116X
Date of Loss:	20/11/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002477

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM9244G	Engine No:	LEB6742959
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU31322951
Reg. Date:	18/07/2019 (Man. Year: 2018)	Odometer:	135063 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,617.84	4,847.52	1,770.32	26.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,990.00	2,040.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,647.84	6,837.52	3,810.32	35.78
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	10,647.84	5,400.00	5,247.84	49.29
+ GST 7.00/7.00% (S\$)	745.35	378.00	367.35	49.29
Nett Amount (S\$)	11,393.19	5,778.00	5,615.19	49.29
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,085.45		

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9244G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,250.30 FL	*1,100.00 FL
2	1		*TAILGATE EMBLEM LOGO	Not Necessary	80.00 FL	*- FL
3	1		*TAILGATE EMBLEM VEZEL	Necessary	76.80 FL	*76.80 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	76.80 FL	*76.80 FL
5	1		*TAILGATE INNER LOCK	Damaged	256.00 FL	*182.00 FL
6	1		*TAILGATE INNER CATCH	Not Necessary	63.00 FL	*- FL
7	1		*TAILGATE INNER HANDLE	Not Necessary	72.00 FL	*- FL
8	1		*TAILGATE REFLECTOR LH	Cracked	318.00 FL	*318.00 FL
9	1		*TAILGATE INNER TRIM	Cracked	310.00 FL	*276.00 FL
10	1		*TAILGATE WEATHERSTRIP	Cut	211.00 FL	*148.00 FL
11	1		*TAILGATE BUZZLE	Not Necessary	160.00 FL	*- FL
12	1		*TAILGATE ALTERNATIVE	Not Necessary	189.30 FL	*- FL
13	1		*TAILGATE WINDSCREEN MOULDING	Necessary	145.00 FL	*145.00 FL
14	1		*REAR BUMPER	Deformed	965.00 FL	*880.00 FL
15	1		*REAR CORNER BUMPER LH	Deformed	290.30 FL	*195.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	112.00 FL	*112.00 FL
17	2		*TAILLAMP LH	Cracked	1,020.00 FL	*474.00 FL
18	2		*REAR FENDER INNER TRIM LH	Cracked	652.00 FL	*326.00 FL
19	1		*REAR END PANEL	Dented	588.30 FL	*588.30 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	136.50 FL	*136.50 FL
21	1		*REAR TOOLS SPONGE TRAY	Cracked	350.00 FL	*350.00 FL
22	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
23	1		*TAILGATE SEALANT	Not Necessary	60.00 FS	*- FS
24	1		*TAILGATE INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
25	1		*TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
26	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*REAR END PANEL TOP CHROME	Necessary	250.00 FS	*120.00 FS
29	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
30	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,082.30	5,924.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,464.46	1,076.88
Total Parts (\$\$)	6,617.84	4,847.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	WIRING CHECK	New	30.00	30.00
4	TUFF COAT	New	100.00	60.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	50.00	50.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	50.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			4,030.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >